

32 Mendota Rd Toronto, ON M8Y 1E8



PREPARED FOR: RANA ALBADRAN

INSPECTION DATE: Sunday, November 7, 2021

PREPARED BY: Siu Leung



Carson, Dunlop & Associates Ltd. 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2

416-964-9415

www.carsondunlop.com inspection@carsondunlop.com

Excellence in home inspection



November 7, 2021

Dear Rana Albadran,

RE: Report No. 79516 32 Mendota Rd Toronto, ON M8Y 1E8

Thank you for choosing us to perform your home inspection. We hope the experience met your expectations.

The enclosed report includes an Overview tab which summarizes key findings, and the report body. The Good Advice tab provides helpful tips for looking after your home; the Reference tab includes a 500-page Reference Library; and the Appendix tab includes valuable added benefits. You can navigate by clicking the tabs at the top of each page.

Please contact us with any questions about the report or the home itself anytime, for as long as you own your home. Our telephone and e-mail consulting services are available at no cost to you. Please watch for your follow-up e-mail. We hope you will complete our short client questionnaire.

Thanks again for choosing Carson Dunlop.

Sincerely,

Siu Leung on behalf of Carson, Dunlop & Associates Ltd.

> Carson, Dunlop & Associates Ltd. 120 Carlton Street, Suite 407 Toronto, ON M5A 4K2 416-964-9415 www.carsondunlop.com inspection@carsondunlop.com

OVERVIEW Report No. 79									
32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.c									ndunlop.com
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

This Overview lists some (if any were identified) of the significant report items. Please read the entire report before making any decisions about the home; do not rely solely on the Overview.

The goal of a home inspection is to identify significant issues that would affect the average person's decision to buy a home. While looking for big issues we typically identify some minor defects along the way. We include these in the report as a courtesy, but please understand a home inspection is not a Technical Audit and does not include a comprehensive list of issues. (That service is available at additional cost.)

When you move into the home you may find some issues not identified in the report. That is to be expected for a number of reasons, such as furniture and storage that has been removed, changes to the property conditions, etc. Therefore, we suggest you allow roughly 1% of the value of the home annually for maintenance and repair.

Plumbing

WATER HEATER \ Life expectancy

Condition: • Near end of life expectancy Task: Replace Time: When necessary Cost: \$1,000 - \$3,000 (Depends on several variables)

WASTE PLUMBING \ Floor drain

Condition: • None noted May be concealed. Location: 2/F laundry room Task: Locate, or provide if missing Time: As soon as practical Cost: \$1,000 and up

Here are a few thoughts to help you stay warm, safe and dry in your home.

All homes require regular maintenance and periodic updates. Maintenance programs help keep homes safe, comfortable and efficient. Roofs, furnaces and air conditioners for example, wear out and have to be replaced. Good maintenance extends the life of these house systems. Refer to Our Advice tab for more details regarding maintenance of your home.

Water is the biggest enemy of homes, whether from leaks through the roof, walls or foundation, or from plumbing inside the home. Preventative maintenance and quick response to water problems are important to minimize damage, costs and help prevent mould.

Environmental consultants can help with issues like mould, indoor air quality and asbestos. If you need help in these areas, we can connect you with professionals.

All recommendations in the report should be addressed by qualified specialists. Our ballpark costs and time frames are

OVERVIEW

32 Mendota Rd, Toronto, ON November 7, 2021

OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

provided as a courtesy and should be confirmed with quotes from specialists. Minor costs in the report are typically under \$1,000.

END OF OVERVIEW

ROOFING	Report No. 79516 www.carsondunlop.com
32 Mendota Rd, Toronto, ON November 7, 2021	www.carsonduniop.com
OVERVIEW ROOFING EXTERIOR STRUCTURE ELECTRICAL	HEATING COOLING INSULATION PLUMBING INTERIOR
OUR ADVICE APPENDIX REFERENCE	
Description	
<text><text></text></text>	

Asphalt shingles

Asphalt shingles

Flat roofing material: • Modified bitumen membrane

Observations and Recommendations

SLOPED ROOF FLASHINGS \ General notes

Condition: • Inspect during annual tune-up.

COMMENTS \ Additional

Condition: • Animal activity or damage (screens added to flashings/roof vents) Task: Monitor / repair Time: Ongoing / regular maintenance

ROOFI									No. 79516
32 Mendot	ta Rd, Toron	to, ON No	vember 7, 20	021				www.carso	ondunlop.com
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							
	- 77	171-70			\leftarrow			1	



Animal activity or damage (screens added to ...

Inspection Methods and Limitations

Roof inspection limited/prevented by: • Deck Inspection performed: • By walking on roof



Animal activity or damage (screens added to ...


Report No. 79516 32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.com overview Roofing Exterior Structure ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR our Advice APPENDIX REFERENCE V V V V

Wall surfaces and trim: • Artificial stone • Brick • EIFS (Exterior Insulation and Finishing System or Synthetic Stucco)

Observations and Recommendations

ROOF DRAINAGE \ Downspouts

Condition: • <u>Connections loose</u> Location: Front Left Side Task: Re - connect Cost: Minor



Connections loose

WALLS \ EIFS (Exterior Insulation and Finishing System) and Stucco

Condition: • Provide annual Stucco "Tune-Up"

WALLS \ Masonry (brick, stone) and concrete

Condition: • Most masonry walls have small cracks due to shrinkage or minor settlement. These will not be individually noted in the report, unless leakage, building movement or similar problems are noted.

DOORS \ General notes

Condition: • Door threshold marginal.

Implication(s): It is more prone to snow buildup/leakage. While it is probably not practical to improve the current situation, it will be important to keep any weatherstripping/door sill in good condition. **Location**: Various

Report No. 79516 www.carsondunlop.com

EXTERIOR

32 Mendota Rd, Toronto, ON November 7, 2021


	,	,							
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							
			NET		-		1999		
			1 - 1	Th					



Example : 2/F rear deck.

LANDSCAPING \ Driveway

Condition: • <u>Uneven (trip hazard)</u> Even the level difference between the garage and the driveway Task: Correct Time: Discretionary Cost: Minor




	EXTERIOR 32 Mendota Rd, Toronto, ON November 7, 2021										
OVERVIEW	ROOFING	EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION	N PLUMBING INTERIOR								
OUR ADVICE	APPENDIX	REFERENCE									

Uneven (trip hazard)

GARAGE \ Vehicle door operators

Condition: • Fails to auto reverse Task: Adjust / Repair Time: If necessary



EXTER 32 Mendot	IOR a Rd, Toron	to, ON No	vember 7, 20)21				•	No. 79516
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE		HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

Inspection Methods and Limitations

Exterior inspected from: • Ground level

Report No. 79516 STRUCTURE www.carsondunlop.com 32 Mendota Rd, Toronto, ON November 7, 2021 ROOFING STRUCTURE ELECTRICAL COOLING INSULATION PLUMBING OUR ADVICE APPENDIX REFERENCE Description Floor construction: • Joists • Subfloor - OSB (Oriented Strand Board) • Not visible in some areas Exterior wall construction: • Wood frame • Wood frame / Brick veneer • Wood frame / Masonry veneer Roof and ceiling framing: • Trusses Plywood sheathing

Plywood sheathing

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • Most foundation walls and masonry walls have small cracks due to minor shrinkage, settlement or shifting. These will not be individually noted, unless leakage or building movement is noted.

FLOORS \ Concrete slabs

Condition: • Concrete basement, crawlspace and garage floors are not typically part of the structure. Almost all basement, crawlspace and garage concrete floors have minor shrinkage and settlement cracks.

Inspection Methods and Limitations

Attic/roof space:
 Inspected from access hatch

Report No. 79516

ELECTRICAL

www.carsondunlop.com

PLUMBING

32 Mendota Rd, Toronto, ON November 7, 2021 OVERVIEW ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION OUR ADVICE APPENDIX REFERENCE


Description

Service size: • 100 Amps (240 Volts)

Main disconnect/service box type and location:
 • <u>Breakers - garage</u>

Distribution panel type and location:

<u>Breakers - garage</u>



Breakers - garage

Distribution wire (conductor) material and type: • Copper - non-metallic sheathed

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):

GFCIs present

The reset button of all GFCI sockets at the rear exterior wall is located at the GFCI socket at the front exterior wall.



Reset button near front door

GFCIs present

The reset button of the GFCI wall sockets of 2/F bathroom and basement powder room is located at the GFCI wall socket

ELECTRICAL 32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondurlop.com OVERVIEW ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING OOLING NSULATION PLUMBING INTERIOR OUR ADVICE APPENDIX REFERENCE at 3/F master bathroom. Image: Comparison of the com

Reset button at 3/F master bathroom

<u>AFCIs present</u>


Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • All electrical recommendations are safety issues. Treat them as high priority items, and consider the Time frame as Immediate, unless otherwise noted.

DISTRIBUTION SYSTEM \ Outlets (receptacles)

Condition: • <u>No GFCI/GFI (Ground Fault Circuit Interrupter)</u> Location: Third Floor Deck Task: Correct Time: As soon as possible Cost: Minor



No GFCI/GFI (Ground Fault Circuit...

Inspection Methods and Limitations

Inspection limited/prevented by: • Main disconnect cover not removed - unsafe to do so.

HEATI 32 Mendot	NG ta Rd, Toron	to, ON No	vember 7, 20)21				•	No. 79516 ndunlop.com
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							
Description									

System type:

• Furnace



Furnace

Fuel/energy source: • Gas

Heat distribution: • Ducts and registers

Approximate capacity: • 66,000 BTU/hr

Efficiency: • <u>High-efficiency</u>

Approximate age: • <u>13 years</u>

Typical life expectancy: • Furnace (high efficiency) 15 to 20 years

Mechanical ventilation system for building: • Kitchen exhaust fan • Bathroom exhaust fan • Laundry room exhaust fan

Observations and Recommendations

FURNACE \ Ducts, registers and grilles

Condition: • Loose register or grille Location: Basement Powder Room Task: Correct Time: As soon as practical Cost: Minor



Loose register or grille

COOLING & HEAT PUMP

Report No. 79516 www.carsondunlop.com

32 Mendota Rd, Toronto, ON November 7, 2021

				voimbol 1, 20	/ _ 1					
	OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
_	OUR ADVICE	APPENDIX	REFERENCE							

Description

Air conditioning type:

• <u>Air cooled</u>



Air cooled

Cooling capacity: • 24,000 BTU/hr

Compressor approximate age: • 13 years

Typical life expectancy: • 10 to 15 years

INSULATION AND VENTILATION 32 Mendota Rd, Toronto, ON November 7, 2021	Report No. 79516 www.carsondunlop.com
OVERVIEW ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION	PLUMBING INTERIOR
OUR ADVICE APPENDIX REFERENCE	
Description	
Attic/roof insulation material: • <u>Cellulose</u>	
Cellulose	
Attic/roof insulation amount/value: • $\frac{R-40}{R-40}$	
Attic/roof air/vapor barrier: • Plastic	
Inspection Methods and Limitations	
Inspection limited/prevented by lack of access to: • Wall space - access not gained.	
Attic inspection performed: • From access hatch	
Roof ventilation system performance: • Not evaluated	

Report No. 79516 www.carsondunlop.com November 7, 2021 ROOFING STRUCTURE ELECTRICAL COOLING INSULATION PLUMBING

PLUMBING 32 Mendota Rd, Toronto, ON

OUR ADVICE APPENDIX REFERENCE Description

Service piping into building: • Plastic

Supply piping in building: • Copper • Plastic

Main water shut off valve at the: • Furnace area

Water heater type:

Induced draft



Induced draft

Water heater fuel/energy source: • Gas Water heater tank capacity: • 189 liters Water heater approximate age: • 15 years Water heater typical life expectancy: • 10 to 15 years Waste and vent piping in building: • Plastic Pumps: • Sump pump Floor drain location: • Utility room

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • Many plumbing fixtures may be expected to last 15 years or more, although faucets are often replaced every 10 years.

WATER HEATER \ Life expectancy

Condition: • Near end of life expectancy Task: Replace Time: When necessary Cost: \$1,000 - \$3,000 (Depends on several variables)

PLUM	BING							Report	No. 79516
32 Mendo	ta Rd, Toron	to, ON No	vember 7, 20)21				www.carso	ndunlop.com
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR


OUR ADVICE APPENDIX REFERENCE

WASTE PLUMBING \ Drain piping - performance

Condition: • The main sewer line to the street cannot be inspected during a home inspection. A video scan dramatically reduces the risk of expensive and unhealthy sewer backups. Bosco provides this \$350 service free of charge to Carson Dunlop clients.

Task: Provide after possession of the home.

Cost: Free from our plumbing business partner - see appendix for deals



Condition: • Leak Location: First Floor Kitchen Task: Repair Time: As soon as possible Cost: Minor

PLUME	BING						Report	No. 79516	
-	a Rd, Toron	ito, ON No	vember 7, 20)21				www.carso	ndunlop.com
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							
		and the							



Leak

WASTE PLUMBING \ Traps - installation

Condition:
 Not visible

Trap not visible - likely behind cabinet finishes (in floor below)

Location: First Floor Kitchen

Task: Monitor for drain performance



Not visible

WASTE PLUMBING \ Floor drain

Condition: • None noted May be concealed. Location: 2/F laundry room Task: Locate, or provide if missing Time: As soon as practical

Report No. 79516

PLUMBING


32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.com									
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

Cost: \$1,000 and up

WASTE PLUMBING \ Sump pump

Condition: • Discharge pipe problems

Discharge point too close to the air conditioner. Relocate the discharge point further away from the air condition unit.





Discharge pipe problems

Condition: • The sump pump was working normally at the time of inspection. With a finished basement, dependable operation is important and the pump should be checked regularly.

Powered by Knowledge

Report No. 79516

PLUMBING


32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.com									
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

Short term improvements would be to clean out any debris from the pit and adjust the float so that the water level stays below the weeping tile.

Other options include backup pumps and/or batteries and high-water alerts.

The extent of the improvements will depend on your comfort level with the system as-is and the level of activity in the sump (i.e. how often does the pump go on). Depending on the geography and water table, some sumps run year-round and others are more seasonal.

The final discharge point should also be identified.



FIXTURES AND FAUCETS \ Faucet

Condition: • Loose faucet Loose faucet and caulking missing. Location: Various Task: Correct Time: As soon as practical Cost: Minor

	PLUMBING 32 Mendota Rd, Toronto, ON November 7, 2021								No. 79516 ondunlop.com
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE	1						
				THE THE					

Example : 3/F master bathroom


Example : 2/F bathroom

Inspection Methods and Limitations

Items excluded from a building inspection: • Tub/sink overflows

INTERIOR	Report No. 79516 www.carsondunlop.com
32 Mendota Rd, Toronto, ON November 7, 2021	
OVERVIEW ROOFING EXTERIOR STRUCTURE ELECTRIC	CAL HEATING COOLING INSULATION PLUMBING INTERIOR
OUR ADVICE APPENDIX REFERENCE	
Observations and Recommendations	
<u>WINDOWS \ Glass (glazing)</u>	
Condition: • Lost seal on double or triple glazing	
Location: Second Floor Rear Room	
Lost seal on double or trip	With the second seco

STAIRS \ Handrails and guards Condition: • Missing Railing missing a t top of wall. Fall hazard for children. Location: First Floor Task: Provide Time: As soon as practical







BASEMENT \ Leakage

Condition: • Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during ourconsultation, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and

INTERIORReport No. 7951632 Mendota Rd, Toronto, ONNovember 7, 2021www.carsondunlop.com

OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

downspouts, and ground sloping down toward the house often cause basement leakage problems. Please read Section 10.0 in the Interior section of the Home Reference Book before taking any action. You can find this in the Reference tab at the end of the report.

To summarize, wet basement issues can be addressed in 4 steps:

1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost)

2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.)

3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$300 to \$600 per crack or hole.)

4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

OUR A	DUR ADVICE Report No. 79516										
32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.com											
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR		
OUR ADVICE	APPENDIX	REFERENCE									

Description

OUR ADVICE FOR LOOKING AFTER YOUR HOME: • Home maintenance is an important responsibility. It protects your investment, extends life expectancy and helps avoid significant expenses. This document is an integral part of the report, and will help you avoid many common problems and reduce costs.

Priority Maintenance and Home Set-Up: • The Home Set-Up and Maintenance chapter in the Home Reference Book provides important information regarding things that are done once when moving in, as well as regular maintenance activities.

Please be sure to follow these maintenance guidelines. The Home Reference Book is included under the REFERENCE tab in this report.

Basement/Crawlspace Leakage: • Basement water leakage is the most common problem with homes. Almost every basement and crawlspace leaks under the right conditions. Good maintenance of exterior grading, gutters and downspouts is critically important.

For more details, please refer to Section 10 of the Interior chapter of the Home Reference Book, which is in the REFERENCE tab in this report.

Roof - Annual Maintenance: • It is important to set up an annual inspection and tune-up program to minimize the risk of leakage and maximize the life of the roof. Roof leaks may occur at any time and are most often at penetrations or changes in material. A leak does not necessarily mean the roof needs to be replaced.

Roof coverings are disposable and have to be replaced from time to time. Asphalt shingles, for example, last roughly 15 years. • Roof coverings are disposable and have to be replaced from time to time. Asphalt shingles, for example, last roughly 15 years.

Exterior - Annual Maintenance: • Annual inspection of the exterior is important to ensure weather-tightness and durability of exterior components. Grading around the home should slope to drain water away from the foundation to help keep the basement dry.

Painting and caulking should be well maintained. Particular attention should be paid to horizontal surfaces where water may collect.

Joints, intersections, penetrations and other places where water may enter the building assembly should be checked and maintained regularly.

Garage Door Operators: • The auto reverse mechanism on your garage door opener should be tested monthly. The door should also reverse when it meets reasonable resistance, or if the 'photo eye' beam is broken.

Electrical System - Label the Panel: • Each circuit in the electrical panel should be labelled to indicate what it controls. This improves both safety and convenience. Where the panel is already labelled, the labelling should be verified as correct. Do not rely on existing labeling.

Ground Fault Circuit Interrupters and Arc Fault Circuit Interrupters: • These should be tested monthly using the test buttons on the receptacles or on the breakers in the electrical panel.

Heating and Cooling System - Annual Maintenance: • Set up an annual maintenance agreement that covers parts and labour for all heating and cooling equipment. This includes gas fireplaces and heaters, as well as furnaces, boilers and air conditioners. Include humidifiers and electronic air cleaners in the service agreement. Arrange the first visit as soon

OUR ADVICE

32 Mendota Rd, Toronto, ON November 7, 2021

OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

as possible after taking possession.

Check filters for furnaces and air conditioners monthly and change or clean as needed. Duct systems have to be balanced to maximize comfort and efficiency, and to minimize operating costs. Adjust the balancing for heating and cooling seasons, respectively.

For hot water systems, balancing should be done by a specialist to due to the risk of leakage at radiator valves. These valves are not operated during a home inspection. • Check filters for furnaces and air conditioners monthly and change or clean as needed. Duct systems have to be balanced to maximize comfort and efficiency, and to minimize operating costs. Adjust the balancing for heating and cooling seasons, respectively. • For hot water systems, balancing should be done by a specialist to due to the risk of leakage at radiator valves. These valves are not operated during a home inspection.

Bathtub and Shower Maintenance: • Caulking and grout in bathtubs and showers should be checked every 6 months, and improved as necessary to prevent leakage and water damage behind walls and below floors.

Water Heaters: • All water heaters should be flushed by a specialist every year to maximize performance and life expectancy. This is even more critical on tankless water heaters.

Washing Machine Hoses: • We suggest braided steel hoses rather than rubber hoses for connecting washing machines to supply piping in the home. A ruptured hose can result in serious water damage in a short time, especially if the laundry area is in or above a finished part of the home.

Clothes Dryer Vents: • We recommend that vents for clothes dryers discharge outside the home. The vent material should be smooth walled (not corrugated) metal, and the run should be as short and straight as practical. This reduces energy consumption and cost, as well as drying time for clothes. It also minimizes the risk of a lint fire inside the vent.

Lint filters in the dryer should be cleaned every time the dryer is used. There is a secondary lint trap in many condominiums. These should be cleaned regularly. There may also a duct fan controlled by a wall switch. The fan should be ON whenever the dryer is used.

Dryer ducts should be inspected annually and cleaned as necessary to help reduce the risk of a fire, improve energy efficiency and reduce drying times.

Fireplace and Wood Stove Maintenance: • Wood burning appliances and chimneys should be inspected and cleaned before you use them, and annually thereafter. We recommend that specialists with a WETT (Wood Energy Technology Transfer, Inc.) designation perform this work. Many insurance companies require a WETT inspection for a property with a wood burning device.

Smoke and Carbon Monoxide (CO) Detectors/Alarms: • Smoke detectors are required at every floor level of every home, including basements and crawlspaces. Even if these are present when you move into the home, we recommend replacing the detectors. We strongly recommend photoelectric smoke detectors rather than ionization type detectors. Carbon monoxide detectors should be provided adjacent to all sleeping areas.

These devices are not tested during a home inspection. Detectors should be tested every 6 months, and replaced every 10 years. Batteries for smoke and carbon monoxide detectors should be replaced annually. If unsure of the age of a smoke detector, it should be replaced.

Report No. 79516 S2 Mendota Rd, Toronto, ON November 7, 2021 overview RooFing EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR OUR ADVICE APPENDIX REFERENCE V

Backwater Valve: • A backwater valve protects your home from a backup of the municipal sewer system. The valve may be equipped with an alarm to notify you of a backup. Please note: if the valve is closed due to a municipal sewer backup, you cannot use the plumbing fixtures in the home. The waste water is unable to leave the building and will back up through floor drains and the lowest plumbing fixtures. • The valve should be inspected and cleaned as necessary at least twice a year.

Sump Pump: • A sump pump collects storm water below the basement floor and discharges it safely to the exterior to prevent flooding. The discharge point should be at least 6 feet (2 m) away from the home. Best installations include backup power for the sump pump, so it will work in the event of a power outage. A high water alarm in the sump pump will notify you if the pump fails. Some installations include a backup pump.

The sump and pump should be inspected and tested four times a year.

For condominium owners: • Condominium owners - Maintenance and Repairs: There are two types of repairs that may be performed in a condo - repairs to an individual condo unit and repairs to common elements. Common elements are set out in the Condominium Declaration and will differ from one building to another. If repairs must be made inside your unit, you are responsible for making the repairs at your own expense. You are also responsible for the ongoing maintenance of your unit. The condominium corporation's board of directors is responsible for maintenance and repair of the common elements. Exclusive-use common elements, such as parking spaces or balconies are generally maintained by the condominium board.

Be Ready for Emergencies: Be sure you know where to shut off the water. Some condos have more than one shut off, and others need a special tool (key) to turn off water. Label each circuit on the electrical panel, and make sure you should know how to turn off the power. Keep a fire extinguisher suitable for grease fires near the kitchen.

Property Manager and Concierge/Security: Keep the contact information for these folks handy (perhaps on your phone) wherever you are. • Lint filters in the dryer should be cleaned every time the dryer is used. There is a secondary lint trap in many condominiums. These should be cleaned regularly. There may also a duct fan controlled by a wall switch. The fan should be ON whenever the dryer is used.

END OF REPORT

APPENDIX Report No. 79516									
	32 Mendota Rd, Toronto, ON November 7, 2021							www.carso	ondunlop.com
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							
			DUNLC /NERS) P Y ASSO	CIATI	ON			

As a Carson Dunlop client, you receive complimentary membership in the Carson Dunlop Homeowners Association. Don't forget to take advantage of all the savings you receive just for being a member.



Free Heating or Cooling Tune-Up from AtlasCare (\$200 value) Get a free safety inspection and tune-up on your home's heating or cooling systems courtesy of our partners at AtlasCare. Claim your \$200 value tune-up by calling **416-626-1785** and ask to speak to a customer service representative about the Carson Dunlop Promo. (Where available)



Free sewer camera inspection from Bosco Home Service (\$350 value) Avoid expensive and unhealthy sewer back-ups! Get a free videoscan on your home's main sewer drain line courtesy of our partners at Bosco Home Services. Claim your free inspection, a \$350 value, by calling **416-626-1785** and ask to speak to a customer service representative about the Carson Dunlop Promo. (Where available)



Our gift to you - a **\$100** Jiffy gift card to use on any Jiffy services. Jiffy connects homeowners to trusted Pros, delivering instant appointments at pre-set, fair rates. The Carson Dunlop team trusts Jiffy to take care of their own homes; that's why we are comfortable recommending Jiffy to you. We love not having to shop for reputable service providers. We also appreciate the speed, quality, and the pricing. You never have to worry about overpaying. To redeem your **\$100 gift card**, simply create an account at jiffyondemand.com or on their iOS or Android app. Then enter your code -CARSON91472 on your first booking. Or enter your code in your Jiffy Profile under credits. It's easy. (where available)




\$100 Gift Card from You Move Me *(Moving Company)* https://www.youmoveme.com/ca/save-100-off-moving-services

APPENDIX 32 Mendota Rd, Toronto, ON	November 7, 2021				No. 79516 ondunlop.com
OVERVIEW ROOFING EXTER		HEATING COOLIN	NG INSULATION	PLUMBING	INTERIOR
OUR ADVICE APPENDIX REFERE	NCE				
	N DUNLOP OWNERS' ASSO	CIATION			
1-8 <u>00-60t-junk?</u> .	\$70 Gift Card from 1-800- (https://www.1800gotjunk.c	-	<u>nlop</u>		
B DAVID SLACK	David Slack Insurance Bro Save 15% off home and aut Brokers. Call 800-971-1363	to insurance with Dav		e	

Questions? Call us at 800-268-7070

Powered by Knowledge



Powered by Knowledge

APPENDIX 32 Mendota Rd, Toronto, ON November 7, 2021	Report No. 79516 www.carsondunlop.com
OVERVIEW ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION	PLUMBING INTERIOR
OUR ADVICE APPENDIX REFERENCE	
Descent Flood Protection Check Take these steps to reduce your risk of basement flooding and reduce the cost of cleaning up after of Remember to check with your municipality about the availability of basement flood protection subscription with your insurer about discounts for taking action to reduce flood risk.	a flood.
1. Maintain Your Home's Flood Protection Features at Least Twice Per Yea	r
SPRING FALL Remove debris from nearest storm drain Clean out eaves troughs Test sump pump(s) and backup power source Clean out backwater valve Maintain plumbing, appliances and fixtures Test flood alarms	
2. Keep Water Out of Your Basement	
 Correct grading to direct water at least 2m away from your foundation Extend downspouts and sump discharge pipes to direct water at least 2m of from your foundation or to the nearest drainage swale Install window well covers Install window wells that are 10–15cm above the ground and are sealed at foundation Install water-resistant basement windows Install a backwater valve (work with a plumber and get required permits) 	
3. Prepare to Remove Any Water from Your Basement as Quickly as Possible	
 Remove obstructions to the basement floor drain Install a back-up sump pump and power source 	
4. Protect Personal Belongings in Your Basement	
 Store valuables in watertight containers or remove Store hazardous materials (paints, chemicals) in watertight containers or r Raise electronics off the floor Select removable area rugs and furnishings that have wooden or metal leg 	
Note: Not all actions will be applicable to each home. Completing these steps does not guarantee the prevention of bo	asement flooding.
	TERLOO
Powered by Knowledge	Page 32 of 45

APPENDIX			Report No. 79516					
	ovember 7, 2021		www.carsondunlop.com					
OVERVIEW ROOFING EXTERIOR	STRUCTURE ELECTRICAL	HEATING COOLING	INSULATION PLUMBING INTERIOR					
OUR ADVICE APPENDIX REFERENCE								
	This is a copy of our home ins							
	the terms, limitations and cond	ditions of the home inspection	on					
THIS CONTRACT LIMITS T	HE LIABILITY OF THE HOME INSPECTI	ON COMPANY.						
PLEASE READ CAREFULLY	BEFORE SIGNING.							
The term Home Inspector	in this document means the Home Ir	spector and the Home Inspecti	on Company. The inspection					
	l accordance with the STANDARDS O		•					
	ards, inspecting every listed item, alt ICE, click <u>http://www.oahi.com/dow</u>	-	-					
The Home Inspector's rep	ort is an opinion of the present condi	tion of the property, based on a	a visual examination of the					
readily accessible features	of the building.							
In addition to the limitatic out in this Agreement.	ns in the STANDARDS, the Inspectior	of this property is subject to Li	mitations and Conditions set					
LIMITATIONS AND CONDI	TIONS OF THE HOME INSPECTION							
The focus of the home ins	pection is on major issues that may a	ffect a reasonable person's dec	ision to buy a home.					
	eralist, rather than a specialist. The h he Inspectors do not perform calculat		-					
structural systems for exa	mple, are properly sized.							
1) THE INSPECTION IS NOT	TECHNICALLY EXHAUSTIVE.							
	ng exercise and is not technically exh come across some smaller issues. The ues will be identified.	-	_					
Establishing the significan be required.	ce of an issue may be beyond the sco	pe of the inspection. Further ev	valuation by a specialist may					
Home Inspection. We hav	e in-depth, technically exhaustive ins e both services available. By acceptin							
Home Inspection instead								
,	t any conditions noted in the Home I ide a more detailed analysis.	nspection Report, we strongly r	ecommend that you consult a					

APPENDIX	Report No. 79516
32 Mendota Rd, Toronto, ON November 7, 2021	www.carsondunlop.com
OVERVIEW ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION	PLUMBING INTERIOR
OUR ADVICE APPENDIX REFERENCE	
2) THE INSPECTION IS AN OPINION OF THE PRESENT CONDITION OF THE VISIBLE COMPONENTS.	
A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings, storage or This includes inaccessible elements such as wiring, heating, cooling, structure, plumbing and insulation.	furniture.
Intermittent problems may not be visible on a Home Inspection because they only happen under certain circumsta example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a tap or appliance is being used in everyday life.	
Home Inspectors will not find conditions that are concealed by finishes, storage or furnishings. Inspectors do not r wall coverings (including wallpaper), lift flooring (including carpet) or move storage or furniture.	emove
Representative sampling is used for components where there are several similar items. The list includes but is not – roof shingles, siding, masonry, windows, interior doors, electrical wiring, receptacles and switches, plumbing pip heating ducts and pipes, attic insulation and air/vapor barriers, and floor, wall and ceiling surfaces.	
3) THIS IS NOT A CODE-COMPLIANCE INSPECTION	
Home Inspectors do NOT determine whether or not any aspect of the property complies with past or present code as building codes, electrical codes, fuel codes, fire codes, etc.), regulations, laws, by-laws, ordinances or other regu requirements. Codes change regularly, and most homes will not comply with current codes.	
4) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.	
This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and formaldehyde based insulation, fiberglass insulation and vermiculite insulation. Inspectors do NOT identify asbestor roofing, siding, wall, ceiling or floor finishes, insulation or fireproofing. Inspectors do NOT look for lead or other to in such things as pipes, paint or window coverings. Health scientists can help in these areas.	os in
The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicide pesticides. Home Inspectors do NOT look for, or comment on, the past use of chemical termite treatments in or ar property.	
5) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.	
The Inspector does not determine if there are irritants, pollutants, contaminants, or toxic materials in or around th building.	ie
The Inspection does not include spores, fungus, mould or mildew. You should note that whenever there is water d noted in the report, there is a possibility that mould or mildew may be present, unseen behind a wall, floor or ceili	-
If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend th consult a qualified Environmental Consultant who can test for toxic materials, mould and allergens at additional co	

APPENDIXReport No.32 Mendota Rd, Toronto, ONNovember 7, 2021www.carsondur	
	ITERIOR
OUR ADVICE APPENDIX REFERENCE	
6) WE DON'T LOOK FOR BURIED TANKS.	
Home Inspectors do not look for fuel oil, septic or gasoline tanks that may be buried on the property. If there are fuel oil or other storage tanks on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to investigate.	
7) CANCELLATION FEE	
If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the fee will apply.	
8) THERMAL IMAGING (If included with this inspection)	
The use of a thermal imager by your home inspector is for the purpose of screening for water leakage issues. While the use of this equipment improves the odds of detecting a moisture issue, it is not a guarantee, as numerous environmental conditions can mask the thermal signature of moisture. Additionally, leakage is often intermittent, and cannot be detected when not present.	
9) MOULD ASSESSMENT (If included with this inspection)	
The services provided include a complete visual inspection from basement to attic for signs of water intrusion and mould growth. Moisture readings will be collected throughout the home. Two indoor air samples and one outdoor reference sample will be collected. Should visible mould growth be identified, one surface sample will be collected. The results of the sample and investigation will be summarized in our written report.	
10) REPORT IS FOR OUR CLIENT ONLY.	
The inspection report is for the exclusive use of the Client named herein, and will not be released to others without the Client's consent. No use of the information by any other party is intended.	
11) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.	
The inspection and report are not a guarantee, warranty or an insurance policy with regard to the fitness of the property.	
12) TIME TO INVESTIGATE	
Home Inspectors will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before they have had a reasonable period of time to investigate.	
13) LIMIT OF LIABILITY	
THE LIABILITY OF THE HOME INSPECTOR AND THE HOME INSPECTION COMPANY ARISING OUT OF THIS INSPECTION AND REPORT, FOR ANY CAUSE OF ACTION WHATSOEVER, WHETHER IN CONTRACT OR IN NEGLIGENCE, IS LIMITED TO A REFUND OF THE FEES THAT YOU HAVE BEEN CHARGED FOR THIS INSPECTION OR \$1,000, WHICHEVER IS GREATER.	
The client agrees that any claim, for negligence, breach of contract or otherwise, be made in writing and reported to Carson Dunlop within 10 business days of discovery. Further, the client agrees to allow Carson Dunlop the opportunity to re- inspect the claimed discrepancy except for an emergency condition, before the client or client's agent, employees or independent contractor repairs, replaces, alters or modifies the claimed discrepancy. The client understands and agrees	

	IDIX a Rd, Toronto, ON November 7, 2021	www.carsondunlop.
VERVIEW	ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING I	INSULATION PLUMBING INTER
R ADVICE	APPENDIX REFERENCE	
	that any failure to notify Carson Dunlop as stated above shall constitute a waiver of any and all cla against the inspector and/or Carson Dunlop.	ims the client may have
	14) TIME PERIOD	
	The Client acknowledges and agrees that the timeframe for commencement of legal proceedings Inspector for damages suffered by the Client as a result of alleged errors, omissions, breaches of c by the Inspector shall not be later than two (2) years from the date of the inspection.	
	15) LEGAL ADVICE	
	The Client has had such legal advice as the Client desires in relation to the effect of this Contract o	n the Client's legal rights.
	16) CLIENT'S AGREEMENT	
	The Client understands and agrees to be bound by each and every provision of this contract. The C bind any other family members or other interested parties to this Contract.	lient has the authority to

APPEN	APPENDIX											
32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.cor												
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR			
OUR ADVICE	APPENDIX	REFERENCE										



Canadian Association Of Home & Property Inspectors

2012 NATIONAL STANDARDS OF PRACTICE

The National Standards of Practice are a set of guidelines for home and property inspectors to follow in the performance of their inspections. They are the most widely accepted Canadian home inspection guidelines in use, and address all the home's major systems and components. The National Standards of Practice and Code of Ethics are recognized by many related professionals as the definitive Standards for professional performance in the industry.

These National Standards of Practice are being published to inform the public on the nature and scope of visual building inspections performed by home and property inspectors who are members of the Canadian Association of Home and Property Inspectors (CAHPI).

The purpose of the National Standards of Practice is to provide guidelines for home and property inspectors regarding both the inspection itself and the drafting of the inspection report, and to define certain terms relating to the performance of home inspections to ensure consistent interpretation.

To ensure better public protection, home and property inspectors who are members of CAHPI should strive to meet these Standards and abide by the appropriate provincial/regional CAHPI Code of Ethics.

These Standards take into account that a visual inspection of a building does not constitute an evaluation or a verification of compliance with building codes, Standards or regulations governing the construction industry or the health and safety industry, or Standards and regulations governing insurability.

Any terms not defined in these Standards shall have the meaning commonly assigned to it by the various trades and professions, according to context.

APPE	APPENDIX Report No. 79516											
32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.com									ndunlop.com			
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR			

OUR ADVICE	APPENDIX	REFERENCE			

INDEX

- Introduction 1.
- 2. Purpose and Scope
- General Limitations and Exclusions 3.
- 4. Structural Systems
- 5. Exterior Systems
- Roof Systems 6.
- 7. Plumbing Systems
- 8. Electrical Systems
- 9 Heating Systems
- 10. Fireplaces & Solid Fuel Burning Appliances
- 11. Air Conditioning Systems
- 12. Interior Systems
- 13. Insulation and Vapour Barriers
- 14. Mechanical and Natural Ventilation Systems

Glossary Note: Italicized words are defined in the Glossary.

1. INTRODUCTION

1.1 The Canadian Association of Home and Property Inspectors (CAHPI) is a not-for-profit association whose members include the following seven provincial/regional organizations: CAHPI-British Columbia., CAHPI-Alberta, CAHPI-Saskatchewan, CAHPI-Manitoba, OAHI (Ontario), AIBO (Quebec), and CAHPI-Atlantic. CAHPI strives to promote excellence within the profession and continual improvement of inspection services to the public.

2. PURPOSE AND SCOPE

2.1 The purpose of these National Standards of Practice is to establish professional and uniform Standards for private, fee-paid home inspectors who are members of one of the provincial/regional organizations of CAHPI. Home Inspections performed to these National Standards of Practice are intended to provide information regarding the condition of the systems and components of the building as inspected at the time of the Home Inspection. This does NOT include building code inspections.

These National Standards of Practice enable the building being inspected to be compared with a building that was constructed in accordance with the generally accepted practices at the time of construction, and which has been adequately maintained such that there is no significant loss of functionality.

It follows that the building may not be in compliance with current building codes, standards and regulations that are applicable at the time of inspection.

These National Standards of Practice apply to inspections of part or all of a building for the following building types:

- single-family dwelling, detached, semidetached or row house
- multi unit residential building
- residential building held in divided or undivided co ownership
- residential building occupied in part for a residential occupancy and in part for a commercial occupancy, as long as the latter use does not exceed 40% of the building's total area, excluding the basement.

2.2 THE INSPECTOR SHALL:

A. inspect:

1. readily accessible, visually observable installed systems, and components of buildings listed in these National Standards of Practice.

B. report:

- 1. on those systems and components installed on the building inspected which, in the professional opinion or judgement of the inspector, have a significant deficiency or are unsafe or are near the end of their service lives.
- 2. a reason why, if not self-evident, the system or component has a significant deficiency or is unsafe or is near the end of its service life.
- 3. the inspector's recommendations to correct or monitor the reported deficiency.
- 4. on any systems and components designated for inspection in these National Standards of Practice which were present at the time of the Home Inspection but were not inspected and a reason they were not inspected.
- 2.3 These National Standards of Practice are not intended to limit inspectors from:
 - A. including other inspection services in addition to those required by these National Standards of Practice provided the *inspector* is appropriately qualified and willing to do so.
 - B. excluding systems and components from the inspection if requested by the client or as dictated by circumstances at the time of the inspection.

3. GENERAL LIMITATIONS AND **EXCLUSIONS**

3.1 GENERAL LIMITATIONS:

- A. Inspections performed in accordance with these National Standards of Practice
- 1. are not technically exhaustive.
- 2. will not identify concealed conditions or latent defects.

APPENDIX Report No. 79516 32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.com

Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.cc									
RVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR

OUR ADVICE APPENDIX REFERENCE

3.2 GENERAL EXCLUSIONS:

- **A.** The *inspector* is not required to perform any action or make any determination unless specifically stated in these National Standards of Practice, except as may be required by lawful authority.
- B. Inspectors are NOT required to determine:
- 1. condition of *systems* or *components* which are not *readily accessible*.
- 2. remaining life of any system or component.
- 3. strength, adequacy, effectiveness, or efficiency of any system or component.
- 4. causes of any condition or deficiency.
- 5. methods, materials, or costs of corrections.
- 6. future conditions including, but not limited to, failure of *systems* and *components*.
- 7. suitability of the property for any use.
- 8. compliance with regulatory requirements (codes, regulations, laws, ordinances, etc.).
- 9. market value of the property or its marketability.
- 10.advisability of the purchase of the property.
- 11.presence of potentially hazardous plants, animals or insects including, but not limited to wood destroying organisms, diseases or organisms harmful to humans.
- 12.presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water, and air.
- 13.effectiveness of any *system* installed or methods utilized to control or remove suspected hazardous substances.
- 14.operating costs of systems or components.
- 15.acoustical properties of any system or component
- 16.design adequacy with regards to location of the home, or the elements to which it is exposed.
- C. Inspectors are NOT required to offer or perform:
- 1. any act or service contrary to law, statute or regulation.
- 2. engineering, architectural and technical services.
- 3. work in any trade or any professional service other than *home inspection*.
- 4. warranties or guarantees of any kind.
- **D.** Inspectors are NOT required to operate:
- 1. any *system* or *component* which is *shut down* or otherwise inoperable.
- 2. any *system* or *component* which does not respond to *normal operating controls*.
- 3. shut-off valves.

E. *Inspectors* are NOT required to enter:

1. any area which will, in the opinion of the *inspector*, likely be hazardous to the *inspector* or other persons or damage the property or its *systems* or *components*.

- 2. confined spaces.
- 3. spaces which are not readily accessible.
- **F.** *Inspectors* are NOT required to *inspect*:
- 1. underground items including, but not limited to storage tanks or other indications of their presence, whether abandoned or active.
- 2. systems or components which are not installed.
- 3. decorative items.
- 4. *systems* or *components* located in areas that are not readily accessible in accordance with these National Standards of Practice.
- 5. detached structures.
- common elements or common areas in multiunit housing, such as condominium properties or cooperative housing when inspecting an individual unit(s), including the roof and building envelope.
- 7. test and/or operate any installed fire alarm system, burglar alarm system, automatic sprinkler system or other fire protection equipment, electronic or automated installations, telephone, intercom, cable/internet systems and any lifting equipment, elevator, freight elevator, wheelchair lift, climbing chair, escalator or others;
- 8. pools, spas and their associated safety devices, including fences.
- **G.** *Inspectors* are NOT required to:
- perform any procedure or operation which will, in the opinion of the *inspector*, likely be hazardous to the *inspector* or other persons or damage the property or it's systems or components.
- 2. move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice, or debris.
- 3. *dismantle* any *system* or *component*, except as explicitly required by these National Standards of Practice.

Report No. 79516

www.carsondunlop.com

32 Mendota Rd. Toronto. ON November 7. 2021

02 11101140													
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR				
OUR ADVICE	APPENDIX	REFERENCE											

4. STRUCTURAL SYSTEMS

4.1 THE INSPECTOR SHALL:

A. inspect:

APPENDIX

- 1. *structural components* including visible foundation and framing.
- 2. by *probing* a sample of structural components where deterioration is suspected or where clear indications of possible deterioration exist. *Probing* is NOT required when *probing* would damage any finished surface or where no deterioration is visible.

B. describe:

- 1. foundation(s).
- 2. floor structure(s).
- 3. wall structure(s).
- 4. ceiling structure(s).
- 5. roof structure(s).

C. report:

- 1. on conditions limiting access to structural components.
- 2. methods used to *inspect* the *under-floor crawl space*
- 3. methods used to *inspect* the attic(s).

4.2 THE INSPECTOR IS NOT REQUIRED TO:

- **A.** provide any *engineering service* or *architectural service*.
- **B.** offer an opinion as to the adequacy of any *structural system* or *component*.

5. EXTERIOR SYSTEMS

5.1 THE INSPECTOR SHALL:

A. inspect:

- 1. exterior wall covering(s), flashing and trim.
- 2. all exterior doors.
- 3. attached or *adjacent* decks, balconies, steps, porches, and their associated railings.
- 4. eaves, soffits, and fascias where accessible from the ground level.
- 5. vegetation, grading, and surface drainage on the property when any of these are likely to adversely affect the building.
- 6. walkways, patios, and driveways leading to dwelling entrances.
- 7. landscaping structure attached or adjacent to the building when likely to adversely affect the building.
- 8. attached garage or carport.
- 9. garage doors and garage door operators for attached garages.

B. describe

- 1. exterior wall covering(s).
- C. report:
 - 1. the method(s) used to inspect the exterior wall elevations.

5.2 THE INSPECTOR IS NOT REQUIRED TO: A. inspect:

- 1. screening, shutters, awnings, and similar seasonal accessories.
- 2. fences.
- 3. geological, geotechnical or hydrological conditions.
- 4. recreational facilities.
- 5. detached garages and outbuildings.
- 6. seawalls, break-walls, dykes and docks.
- 7. erosion control and earth stabilization measures.

6. ROOF SYSTEMS

6.1 THE INSPECTOR SHALL:

A. inspect:

- 1. readily accessible roof coverings.
- 2. readily accessible roof drainage systems.
- 3. *readily accessible* flashings.
- 4. *readily accessible* skylights, chimneys, and roof penetrations.

B. describe

- 1. roof coverings.
- C. report:
 - 1. method(s) used to inspect the roof(s).

6.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. antennae and satellite dishes.
- 2. interiors of flues or chimneys.
- 3. other *installed* items attached to but not related to the roof system(s).

7. PLUMBING SYSTEMS

7.1 THE INSPECTOR SHALL:

A. inspect:

- 1. interior water supply and distribution *systems* including all fixtures and faucets.
- 2. drain, waste and vent *systems* including all fixtures.
- 3. water heating equipment and associated venting systems.
- 4. water heating equipment fuel storage and fuel distribution systems.
- 5. fuel storage and fuel distribution systems.
- 6. drainage sumps, sump pumps, and related
- piping.

B. describe:

- 1. water supply, distribution, drain, waste, and vent piping materials.
- 2. water heating equipment including the energy source.
- 3. location of main water and main fuel shut-off valves.

2 Mendot	a Rd, Toron	to, ON Nov	vember 7, 2021				www.carsor	ndunlop.c
VERVIEW	ROOFING	EXTERIOR	STRUCTURE ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERI
R ADVICE	APPENDIX	REFERENCE						
	7.2 THE INS	PECTOR IS NC	T REQUIRED TO:	5. telecor B. measure :	nmunication	equipment.		
	1. clothes 2. wells, w	vell pumps, or v	ne connections. ⁄ater storage related			or impedance.		
		onditioning sys		9. HEATIN	NG SYSTE	MS		
		ater heating sys lawn sprinkler		9 1 THE IN	SPECTOR SH	AI I ·		
		waste disposal		A. inspect:				
	B. determine	:	-			omponents of <i>in</i>	stalled	
			and waste disposal		g equipment.	· · ·] ·]·:		
		are public or p	orivate. of the water supply.			and chimneys. I distribution sy	rstems	
	C. operate:	intity of quality	of the water suppry.	B. describe:		and an and a standard	stems.	
		alves or shut-o	ff valves.	01	source(s).			
						y distinguishing	5	
	8 FLECTE	RICAL SYST	FMS		teristics.	enting material(e)	
	O. LLLCIN				stion air soui		5).	
		PECTOR SHAL	L:			thods (naturally	aspiring,	
	A. inspect: 1. service	drop				t vent, direct vei	nt sealed	
			ctors, cables, and	combu	stion).			
	raceway			9.2 THE IN	SPECTOR IS		о то:	
			main disconnects.	A. inspect:				
	4. service				rs of flues or	chimneys.		
	5. interior panels.	components of	service panels and sub		changers.			
		tion conductor	S.		ry equipment nic air filters			
		rent protection			leating system			
			er of installed lighting	or border in				
		, switches, and		B. determin				
	appropr	riate).	errupters (GFCI) (if upters (AFCI) (if	1. system	adequacy or	distribution ba	lance.	
	appropr		ipters (APCI) (II					
	B. describe:				ING APPL	ND SOLID FL	JEL	
			rating of the service.			thority having jur	isdiction)	
	2. location 3. <i>wiring</i> (nnect(s) and subpanel(s).	-	-			
	C. report:	meinous.		_	NSPECTOR S	HALL:		
	-	e of solid condu	ıctor aluminum branch	A. inspect:	components			
	circuit v	wiring.		*	stems and ch	imneys		
		e of carbon mon	oxide detectors (if appli-	B. describe:		-		
	cable).	of smoke dete	tors			fuel burning app	oliances	
			lt circuit interrupters	2. chimne	ys			
	(GFCI).	8		10.2 THE	INSPECTOR I	S NOT REQUIR	ED TO:	
	5. presenc	e of arc fault ci	rcuit interrupters (AFCI).	A. inspect:				
				1. interior	of flues or ch			
	8.2 THE INC		T REQUIRED TO:		, doors and d	ampers		
	A. inspect:		T REGUILED TO.		nd gaskets atic fuel feed o	devices		
	1. remote only cor	ntrol device.	unless the device is the	5. heat die or grav	stribution ass ity	sists whether fai	n assisted	
		ystems and con			extinguish fir			
			<i>tems</i> and <i>components</i> . <i>ns</i> and <i>components</i> not a		e draught cha			
			ctrical power distribution	ם. move fire	piace inserts	, stoves, or firebo	ox contents	
	system.	- *	_					

Report No. 79516 APPENDIX www.carsondunlop.com 32 Mendota Rd, Toronto, ON November 7, 2021 COOLING INSULATION ROOFING STRUCTURE PLUMBING OUR ADVICE REFERENCE APPENDIX **11. AIR CONDITIONING SYSTEMS** 13.2 THE INSPECTOR IS NOT REQUIRED TO: A. disturb 1. insulation. **11.1 THE INSPECTOR SHALL:** A. inspect 2. vapour barriers. 1. permanently *installed* central air conditioning B. obtain sample(s) for analysis equipment. 1. insulation material(s). **B. describe:** 1. energy source. 14. MECHANICAL AND NATURAL 2. cooling method by its distinguishing characteristics. VENTILATION SYSTEMS 14.1 THE INSPECTOR SHALL: 11.2 THE INSPECTOR IS NOT REQUIRED TO: A. inspect: A. inspect 1. ventilation of attics and foundation areas. 1. electronic air filters. 2. portable air conditioner(s). 2. mechanical ventilation systems. 3. ventilation systems in areas where moisture is **B. determine:** generated such as kitchen, bathrooms, laundry 1. system adequacy or distribution balance. rooms. **B. describe: 12. INTERIOR SYSTEMS** 1. ventilation of attics and foundation areas. 12.1 THE INSPECTOR SHALL: 2. mechanical ventilation systems. A. inspect: 3. ventilation systems in areas where moisture 1. walls, ceilings, and floors. is generated such as: kitchens, bathrooms and 2. steps, stairways, and railings. laundry rooms. 3. a representative number of countertops and C. report: installed cabinets. 1. absence of ventilation in areas where moisture 4. a representative number of doors and windows. is generated such as: kitchens, bathrooms and 5. walls, doors and ceilings separating the laundry rooms. habitable spaces and the garage. **B. describe:** 14.2 THE INSPECTOR IS NOT REQUIRED TO: 1. materials used for walls, ceilings and floors. 1. determine indoor air quality. 2. doors. 2. determine system adequacy or distribution 3. windows. balance. C. report 1. absence or ineffectiveness of guards and handrails or other potential physical injury hazards. 12.2 THE INSPECTOR IS NOT REQUIRED TO: A. inspect: 1. *decorative* finishes. 2. window treatments. 3. central vacuum systems. 4. household appliances. 5. recreational facilities. **13. INSULATION AND VAPOUR BARRIERS 13.1** THE INSPECTOR SHALL: A. inspect: 1. insulation and vapour barriers in unfinished spaces. **B. describe:** 1. type of insulation material(s) and vapour barriers in unfinished spaces.

- C. report
 - 1. absence of insulation in unfinished spaces within the building envelope.
 - 2. presence of vermiculite insulation

	APPENDIX											
32 Mendota Rd, Toronto, ON November 7, 2021 www.carsondunlop.com												
OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR			

GLOSSARY

APPENDIX

Adjacent

OUR ADVICE

Nearest in space or position; immediately adjoining without intervening space.

REFERENCE

Alarm Systems

Warning devices, installed or free-standing, including but not limited to; carbon monoxide detectors, flue gas and other spillage detectors, security equipment, ejector pumps and smoke alarms.

Architectural Service

Any practice involving the art and science of building design for construction of any structure or grouping of structures and the use of space within and surrounding the structures or the design for construction, including but not specifically limited to, schematic design, design development, preparation of construction contract documents, and administration of the construction contract, adequacy of design for the location and exposure to the elements.

Automatic Safety Controls

Devices designed and installed to protect *systems* and *components* from unsafe conditions.

Component

A part of a system.

Confined Spaces

An enclosed or partially enclosed area that: 1. Is occupied by people only for the purpose of completing work.

2. Has restricted entry/exit points.

3. Could be hazardous to people entering due to:

a. its design, construction, location or atmosphere. b. the materials or substances in it, or

b. the materials of substances in it, of

c. any other conditions which prevent normal inspection procedure.

Decorative

Ornamental; not required for the operation of the essential *systems* and *components* of a building.

Describe

To *report* a *system* or *component* by its type or other observed, significant characteristics to distinguish it from other *systems* or *components*.

Determine

To find out, or come to a conclusion by investigation.

Dismantle

To take apart or remove any component, device, or piece of equipment that would not be taken apart or removed by a homeowner in the course of normal and routine home owner maintenance.

Engineering Service

Any professional service or creative work requiring engineering education, training, and experience and the application of special knowledge of the mathematical, physical and engineering sciences to such professional service or creative work as consultation, investigation, evaluation, planning, design and supervision of construction for the purpose of assuring compliance with the specifications and design, in conjunction with structures, buildings, machines, equipment, works or processes.

Functionality

The purpose that something is designed or expected to fulfill.

Further Evaluation

Examination and analysis by a qualified professional, tradesman or service technician beyond that provided by the *home inspection*.

Home Inspection

The process by which an *inspector* visually examines the *readily accessible systems* and *components* of a building and which *describes* those *systems* and *components* in accordance with these National Standards of Practice.

Household Appliances

Kitchen, laundry, and similar appliances, whether *installed* or freestanding.

Inspect

To examine *readily accessible systems* and *components* of a building in accordance with these National Standards of Practice, *where applicable* using *normal operating controls* and opening *readily openable access panels*.

Inspector

A person hired to examine any *system* or *component* of a building in accordance with these National Standards of Practice.

Installed

Set up or fixed in position for current use or service.

Monitor

Examine at regular intervals to detect evidence of change.

Normal Operating Controls

Devices such as thermostats, switches or valves intended to be operated by the homeowner.

Operate

To cause to function, turn on, to control the function of a machine, process, or system.

NATIONAL STANDARDS OF PRACTICE. © COPYRIGHT 2012 CANADIAN ASSOCIATION OF HOME & PROPERTY INSPECTORS. ALL RIGHTS RESERVED.

IN TOPAC

Report No. 79516

www.carsondunlop.com

APPENDIX

32 Mendota Rd, Toronto, ON November 7, 2021

OVERVIEW	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
OUR ADVICE	APPENDIX	REFERENCE							

Probing

Examine by touch.

Readily Accessible

Available for visual inspection without requiring moving of personal property, *dismantling*, destructive measures, or any action which will likely involve risk to persons or property.

Readily Openable Access Panel

A panel provided for homeowner inspection and maintenance that is within normal reach, can be removed by one person, and is not sealed in place.

Recreational Facilities

Spas, saunas, steam baths, swimming pools, exercise, entertainment, athletic, playground or other similar equipment and associated accessories.

Report

To communicate in writing.

Representative Number

One *component* per room for multiple similar interior *components* such as windows and electric outlets; one *component* on each side of the building for multiple similar exterior *components*.

Roof Drainage Systems

Components used to carry water off a roof and away from a building.

Sample

A representative portion selected for inspection.

Service Life/Lives

The period during which something continues to function fully as intended.

Significant Deficiency

A clearly definable hazard or a clearly definable potential for failure or is unsafe or not functioning.

Shut Down

A state in which a *system* or *component* cannot be operated by *normal operating controls*.

Solid Fuel Burning Appliances

A hearth and fire chamber or similar prepared place in which a fire may be built and which is built in conjunction with a chimney; or a listed assembly of a fire chamber, its chimney and related factory-made parts designed for unit assembly without requiring field construction.

Structural Component

A component that supports non-variable forces or weights (dead loads) and variable forces or weights (live loads).

System

A combination of interacting or interdependent components, assembled to carry out one or more functions.

Technically Exhaustive

An inspection is technically exhaustive when it is done by a specialist who may make extensive use of measurements, instruments, testing, calculations, and other means to develop scientific or engineering findings, conclusions, and recommendations.

Under-floor Crawl Space

The area within the confines of the foundation and between the ground and the underside of the floor.

Unsafe

A condition in a *readily accessible, installed system* or *component* which is judged to be a significant risk of personal injury during normal, day-to-day use. The risk may be due to damage, deterioration, missing or improper installation or a change in accepted residential construction Standards.

Vapour Barrier

Material used in the building envelope to retard the passage of water vapour or moisture.

Visually Accessible

Able to be viewed by reaching or entering.

Wiring Methods

Identification of electrical conductors or wires by their general type, such as "non-metallic sheathed cable" ("Romex"), "armored cable" ("bx") or "knob and tube", etc.

Note - In these National Standards of Practice, redundancy in the description of the requirements, limitations and exclusions regarding the scope of the Home Inspection is provided for clarity not emphasis.

(CAHPI acknowledges The American Society of Home Inspectors®, Inc. (ASHI®) for the use of their Standards of Practice (version January 1, 2000)

(AUGUST 22/12 VER. F)

Report No. 79516

REFERENCE LIBRARY www.carsondunlop.com 32 Mendota Rd, Toronto, ON November 7, 2021 ROOFING STRUCTURE COOLING INSULATION PLUMBING OUR ADVICE APPENDIX REFERENCE The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report. Click on any link to read about that system. 01. ROOFING, FLASHINGS AND CHIMNEYS (\gg) 02. EXTERIOR (>>) (\gg) 03. STRUCTURE 04. ELECTRICAL (\mathcal{S}) 05. HEATING (>>) (\gg) 06. COOLING/HEAT PUMPS (\gg) 07. INSULATION (>>)08. PLUMBING (\gg) 09. INTERIOR (\gg) **10. APPLIANCES 11. LIFE CYCLES AND COSTS** >>> **12. SUPPLEMENTARY** Asbestos Radon Urea Formaldehyde Foam Insulation (UFFI) Lead Carbon Monoxide Mold **Household Pests Termites and Carpenter Ants 13. HOME SET-UP AND MAINTENANCE 14. MORE ABOUT HOME INSPECTIONS**

Powered by Knowledge