

Your Inspection Report



140 Jones Ave
Toronto, ON M4M 3A1



PREPARED FOR:
DERRICK TSE

INSPECTION DATE:
Friday, March 13, 2026

PREPARED BY:
Gordon Mathieu, B.Sc Elec Eng., RHI



Carson, Dunlop & Associates Ltd.
120 Carlton Street, Suite 407
Toronto, ON M5A 4K2

416-964-9415
www.carsondunlop.com
inspection@carsondunlop.com

Excellence in home inspection



March 26, 2026

Dear Derrick Tse,

RE: Report No. 96443, v.2
140 Jones Ave
Toronto, ON
M4M 3A1

Thank you for choosing us to perform your home inspection. We hope the experience met your expectations.

The enclosed report includes an Overview tab which summarizes key findings, and the report body. The Good Advice tab provides helpful tips for looking after your home; and the Appendix tab includes valuable added benefits. You can navigate by clicking the tabs at the top of each page.

TO THE PROSPECTIVE BUYER: Our obligation and liability are limited to the seller.

Thanks again for choosing Carson Dunlop

Sincerely,

Gordon Mathieu, B.Sc Elec Eng., RHI
on behalf of
Carson, Dunlop & Associates Ltd.

Carson, Dunlop & Associates Ltd.
120 Carlton Street, Suite 407
Toronto, ON M5A 4K2
416-964-9415
www.carsondunlop.com
inspection@carsondunlop.com

OVERVIEW

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

This Overview lists some of the significant report items if any were identified. Please read the entire report before making any decisions about the home; do not rely solely on the Overview.

FOR THE BUYER

There are two elements to a home inspection - the inspection itself and the report. This report is helpful, but the inspection is equally important. You need both elements to make an informed decision.

When you move into the home you may find some issues not identified in the report. That is to be expected for a few reasons, such as furniture and storage that has been removed, changes to the property conditions, etc. Therefore, we suggest you allow roughly 1% of the value of the home annually for maintenance and repair.

Our obligation and liability are limited to the seller.

Roofing

RECOMMENDATIONS \ General

Condition: • The roof was partially covered with snow, and could not be fully inspected.

The condition of the roof covering were not determined.

Task: Further evaluation by a specialist when weather permits.

Time: As soon as practical

Cooling & Heat Pump

RECOMMENDATIONS \ General

Condition: • There is no air conditioning.

Task: Provide

Time: As required

Cost: \$5,000 - and up

Here are a few thoughts to help you stay warm, safe and dry in your home.

All homes require regular maintenance and periodic updates. Maintenance programs help keep homes safe, comfortable and efficient. Roofs, furnaces and air conditioners for example, wear out and have to be replaced. Good maintenance extends the life of these house systems. Refer to Our Advice tab for more details regarding maintenance of your home.

Water is the biggest enemy of homes, whether from leaks through the roof, walls or foundation, or from plumbing inside the home. Preventative maintenance and quick response to water problems are important to minimize damage, costs and help prevent mould.

Environmental consultants can help with issues like mould, indoor air quality and asbestos. If you need help in these areas, we can connect you with professionals.

OVERVIEW

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

All recommendations in the report should be addressed by qualified specialists. Our ballpark costs and time frames are provided as a courtesy and should be confirmed with quotes from specialists. Minor costs in the report are typically under \$1,000.

END OF OVERVIEW

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

Description

Sloped roofing material:

- Asphalt shingles

The sellers stated that it was replaced in 2020: ask for the invoice & warranty.

Flat roofing material:

- Modified bitumen membrane

The sellers stated that it was replaced in 2020: ask for the invoice & warranty.

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • The roof was partially covered with snow, and could not be fully inspected.

The condition of the roof covering were not determined.

Task: Further evaluation by a specialist when weather permits.

Time: As soon as practical

Inspection Methods and Limitations

Inspection limited/prevented by: • Lack of access (Environmental - wind/rain/snow/ice)

Inspection performed: • With binoculars

Description

Wall surfaces and trim: • [Artificial stone](#) • [Asphalt shingles](#) • [Metal siding](#) • [Vinyl siding](#)

Observations and Recommendations

ROOF DRAINAGE \ Downspouts

Condition: • Downspout discharge point could not be observed due to snow. Ensure they are discharging above grade and 4-6 feet away from the home.

Location: Throughout

Task: Verify

Time: In the spring

WALLS \ Flashings and caulking

Condition: • The gap at the wall should be well sealed.

Location: Various

Task: Improve

Time: Regular maintenance



WALLS \ Masonry (brick, stone) and concrete

Condition: • Masonry deterioration

Location: Front

Task: Repair

Time: As required

Cost: Not determined

EXTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

| | | | | | | | | | |
|-----------|------------|-----------------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



Masonry deterioration: front

Rear


Condition: • Parging damaged or missing

Location: Rear

Task: Improve

Time: As required

Cost: Not determined



EXTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE



Parging damaged or missing

WALLS \ Vent (fan, clothes dryer, etc.)

Condition: • Cover missing

Location: Front of Home

Task: Provide

Time: As required

Cost: Minor



Cover/flap missing

Condition: • Seal - ineffective

Location: Upper rear

Task: Seal

Time: As soon as practical

Cost: Minor

EXTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



Seal - ineffective


WINDOWS \ General notes

Condition: • Paint and caulking - deteriorated / missing

Location: Various

Task: Improve

Time: As required



Paint and caulking - deteriorated / missing



EXTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE



Paint and caulking - deteriorated / missing

Condition: • Sill close to grade

Location: Front of Home

Task: Inspect and sweep/shovel

Time: Regular maintenance



EXTERIOR \ Window wells

Condition: • Missing

Location: Rear

EXTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR


RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

Task: Provide
Time: As required
Cost: Minor



Missing

DOORS \ General notes

Condition: • Paint or stain - needed
...and caulking.

Location: Rear

Task: Improve

Time: Regular maintenance

EXTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE



Paint or stain - needed

Condition: • Damage

Location: Front of Home

Task: Repair

Time: As required




PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ General notes

Condition: • The quality of the connection of a deck to the building is a common issue. This cannot be verified during a home inspection, but you should understand this is a potential weak spot in any deck system.

Task: Inspect Annually

Time: Ongoing



BASEMENT WALKOUTS \ General notes


Condition: • Guard / handrail - missing

Task: Provide

Time: As soon as possible

Cost: Minor


| | | | | | | | | | |
|-----------|------------|-----------------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



Guard / handrail - missing

Condition: • Drain - missing
Task: Provide
Time: As required
Cost: Not determined

| | | | | | | | | | |
|-----------|------------|-----------------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



Drain - missing

Condition: • The walkout is no longer in use.

Location: Rear Basement



LANDSCAPING \ Lot grading

Condition: • Grade could not be determined due to snow

Ensure grading around the home is sloped away from the foundations.

Location: Various Exterior

Task: Verify

Time: In spring

Inspection Methods and Limitations

Inspection limited/prevented by: • Poor access under steps, deck, porch • Lack of access - Environmental (snow/ice) • Gutters and downspouts may be obstructed by ice or snow, limited evaluation of performance and draining at time of the inspection.

Exterior inspected from: • Ground level

Description

General: • The structure has performed well, with no evidence of significant movement.

Configuration: • [Basement](#)

Foundation material:

• [Brick](#)

Not visible in some places.

Floor construction: • [Joists](#) • [Concrete](#)

Exterior wall construction: • [Wood frame](#) • [Wood frame / Brick veneer](#) • Wood frame / Masonry veneer

Roof and ceiling framing:

• [Rafters/roof joists](#)

Not visible in the attic, no access.

• [Rafters/roof joists](#)

As seen in the rear knee wall.



Rafters/roof joists



Rafters/roof joists

Party wall: • [Not visible](#)

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • Most foundation walls and masonry walls have small cracks due to minor shrinkage, settlement or shifting. These will not be individually noted, unless leakage or building movement is noted.

FLOORS \ Concrete slabs

Condition: • Concrete basement, crawlspace and garage floors are not typically part of the structure. Almost all basement, crawlspace and garage concrete floors have minor shrinkage and settlement cracks.

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

Inspection Methods and Limitations

Attic/roof space: • No access • Cathedral roof - no access

Knee wall areas: • Inspected from access hatch

Description

General:

- The electrical system has been substantially updated.




The electrical system has been s

Service size: • [100 Amps \(240 Volts\)](#)

Main disconnect/service box type and location: • [Breakers - basement](#)

Distribution panel type and location:

- [Breakers - basement](#)



Breakers - basement

Auxiliary panel (subpanel) type and location:

- [Breakers - basement](#)


| | | | | | | | | | |
|-----------|------------|----------|-----------|-------------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



Breakers - basement

Distribution wire (conductor) material and type: • [Copper - non-metallic sheathed](#) • [Copper - metallic sheathed](#)

Distribution wire (conductor) material and type: • Bonding strap noted.



Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • [GFCIs present](#) • No AFCI

Observations and Recommendations

DISTRIBUTION SYSTEM \ Knob-and-tube wiring (wires)

Condition: • [Although no active knob-and-tube wiring was noted there may be some present based on the age of the home.](#) Click on the line above to see the Ontario Electrical Safety Authority's position on this wiring system.

Task: Further evaluation / Improve

Time: If necessary

Cost: Not determined

DISTRIBUTION SYSTEM \ Wiring - installation, damaged or exposed


Condition: • Exposed on walls or ceilings

Location: Various

Task: Improve

Time: As required

Cost: Not determined



DISTRIBUTION SYSTEM \ Outlets (receptacles)

Condition: • Adding Ground Fault Circuit Interrupters (GFCIs) is a cost-effective safety improvement to existing homes. At an installed cost of roughly \$100 each, they provide enhanced protection against electric shock and are particularly useful near wet areas like outdoors, garages, and bathrooms). GFCIs may be either special circuit breakers or special wall outlets (receptacles). Either one protects all downstream outlets on that circuit.

Task: Provide

Time: When renovating

Cost: Minor

Condition: • Adding ARC Fault Circuit Interrupters (AFCIs) is a cost-effective safety improvement to existing homes. AFCI's are a circuit breaker in the electrical panel> When installed they provide enhanced protection by detecting an electric arc in the circuit and will "trip or shut off" the circuit to prevent electrical fires. (cost of roughly \$100 each). They could be installed in all the bedroom circuits (as an improvement only).

Location: Panel

Task: Provide as an improvement only

Time: When renovating

DISTRIBUTION SYSTEM \ Switches

Condition: • Poor installation.

Location: First Floor

Task: Improve

Time: As required



DISTRIBUTION SYSTEM \ Lights

Condition: • Exposed to mechanical damage (No cage or protective lens).

Location: Various

Task: Protect

Time: As soon as practical

Cost: Minor

Inspection Methods and Limitations

Inspection limited/prevented by: • Main disconnect cover not removed - unsafe to do so.

Description

Heating system type:

- [Furnace](#)



Furnace

Fuel/energy source: • [Gas](#)

Approximate capacity: • [60,000 BTU/hr](#)

Efficiency: • [High-efficiency](#)

Approximate age: • [8 years](#)

Typical life expectancy: • Furnace (high efficiency) 15 to 20 years

Main fuel shut off at: • Meter

Auxiliary heat:

- [Electric heater](#)

In the front porch/shared laundry room.

HEATING

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



Electric heater

Fireplace/stove: • None

Exhaust/Chimney/vent:

- [Masonry](#)

Rear: no longer in use by this semi.



Blocked off in the basement



Masonry

Humidifier: • [Duct mounted bypass humidifer](#)

Mechanical ventilation system for building: • Bathroom exhaust fan

| | | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|----------|----------|--|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | | |

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • It is common to feel the airflow stronger at some registers, depending on the length of the ductwork and the number of turns required to get there. Different preferences and seasons often necessitate different setups (balancing). A service agreement that covers parts and labour (for heating and cooling equipment) is typically advised.


Location: Throughout

Task: Monitor / improve

FURNACE \ Electronic air cleaner

Condition: • [Missing components](#)

Not in use anymore. The original electronic air filter components have been removed. Now in place is a thin passive filter. A much wider one is recommended for better performance.





Missing components

FURNACE \ Ducts, registers and grilles

Condition: • Ductwork - layout typical of older houses

Task: Further evaluation / Improve

Time: As required

Condition: • [Excessively long runs, excessive elbows](#)


Location: For example, Third Floor

Task: Further evaluation / Improve

Time: As required

Cost: Not determined

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|----------------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



CHIMNEY AND VENT \ Masonry chimney cap (crown)

Condition: • Missing


A cap (crown) would protect and prolong the life of the chimney.

Task: Provide

Time: Discretionary

Cost: \$1,000 to \$2,500 (depending on several variables)

What makes a good chimney cap?



Inspection Methods and Limitations

General: • The inspection does not include gas leak detection, carbon monoxide testing, combustion analysis, or evaluation of internal furnace components.

Inspection limited by: • Top of chimney not inspected due to height

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • There is no air conditioning.

Task: Provide

Time: As required

Cost: \$5,000 - and up

AIR CONDITIONING \ General notes

Condition: • In homes where air conditioning is not present or not effective in some areas, supplemental cooling can be provided with a ductless air conditioning system. Portable window air conditioners are available, but there are also more sophisticated split systems, with an outdoor unit and an indoor (or through-the-wall) unit. These systems can help improve the comfort of a home. In most cases, you won't know whether such a unit is necessary until you have lived in the home for some time.

Task: Further evaluation / Improve

Time: As required

Cost: Not determined

Description

Attic/roof insulation material: • Not visible

Attic/roof insulation amount/value: • [Not visible](#)

Attic/roof air/vapor barrier: • [Not visible](#)

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • We recommend that access be provided into the attic so the area can be inspected. Access may provide information about insulation and ventilation, structure, and concealed problems.

Task: Provide

Time: As required

Cost: Minor

ATTIC/ROOF \ Insulation

Condition: • [Exposed combustible insulation](#)

Location: Rear Third Floor

Task: Improve

Time: As required



Exposed combustible insulation



Exposed combustible insulation

ATTIC/ROOF \ Roof vents

Condition: • Ventilation suspect

Ventilation is a key component in the effort to keep mould/mildew from forming in an attic.

It is hard to have too much ventilation; it doesn't matter how cold the attic space is (assuming there is lots of insulation keeping the house warm). Good ventilation will also help keep the heat down in the summer (especially with dark shingles).


A clear path for any soffit venting should be ensured (add baffles if necessary) and the roof vents should be checked for obstruction (sometimes the holes in the sheathing are not fully cut out).

Any exhaust fan should have a dedicated, insulated duct that goes to a separate roof vent.

A good time to check for excessive humidity in the attic is in the winter; it will appear as frost on the roof sheathing.

Task: Engage roofing specialist to inspect and advise.

Time: As soon as practical



Inspection Methods and Limitations

Inspection limited/prevented by lack of access to: • Roof space

Inspection limited/prevented by lack of access to: • Wall space - access not gained

Roof ventilation system performance: • Not evaluated

Description

General: • Several fixtures have been updated. • The kitchen and bathrooms have been updated.

Service piping into building:

- [Copper](#)

What's visible is copper.



Copper

Supply piping in building:

- [Copper](#)
 - PEX (cross-linked Polyethylene)
- Brand not visible.

Supply piping in building: • Not visible in most areas.

Main water shut off valve at the: • Front of the basement

Water heater type:

- [Induced draft](#)
- Tank



Tank

Water heater fuel/energy source: • [Gas](#)

Water heater tank capacity: • 189 liters/50 US gallons

Water heater approximate age: • 7 years

Water heater typical life expectancy: • 10 to 15 years

Waste and vent piping in building: • [Plastic](#) • [Cast iron](#)

Waste and vent piping in building: • Not visible in most areas.

Pumps: • None

Floor drain location:

- Center of basement
- ...in the bathroom.

Backwater valve: • None noted

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • Many plumbing fixtures may be expected to last 15 years or more, although faucets are often replaced every 10 years.

SUPPLY PLUMBING \ Water supply piping in building

Condition: • Functional water pressure.

Task: Upgrade

Time: As required

Cost: Not determined

WATER HEATER \ General notes

Condition: • Mixing/tempering valve - not present

*Recommended to reduce risk of scalding

Task: Provide

Time: When updating

Cost: Minor

WASTE PLUMBING \ Drain piping - installation


Condition: • Clean-outs missing or inaccessible


May be concealed.

Task: Locate, or provide if missing

Time: Discretionary.

Cost: Minor if a clean out is in place (typical). Up to \$1000 if there is none.





WASTE PLUMBING \ Drain piping - performance

Condition: • The main sewer line to the street cannot be inspected during a home inspection. A video scan dramatically reduces the risk of expensive and unhealthy sewer back-ups.

Task: Provide after possession of the home.

Cost: \$300 and up


Condition: • The cast iron waste piping is near the end of its normal life expectancy and is prone to rusting through or splitting. Replacement may be required in the near future.

Task: Further evaluation Replace

Time: As required

Cost: Not determined

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|-----------------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |



WASTE PLUMBING \ Traps - installation

Condition: • S-trap noted.

Location: Basement Bathroom

Task: Improve

Time: As required



WASTE PLUMBING \ Backwater valve

Condition: • None noted


Adding a backwater valve to the main drain line is an improvement you may consider to help protect your home against sewer backups. Some municipalities provide rebates or financial assistance for installing these devices. Some insurance companies offer premium discounts or other benefits for homeowners with backwater valves. The cost is typically \$2,000 to \$4,000, with \$2,500 being a common number. Once installed, they should be inspected twice annually.

Location: Basement

Task: Provide

Time: Discretionary

Cost: \$2,000 - \$4,000



FIXTURES AND FAUCETS \ Shower stall enclosure

Condition: • Caulking and grout should be checked every six months and improved as necessary to prevent leakage and damage behind wall surfaces.

Location: Various

Task: Improve

Time: Regular maintenance

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|-----------------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |

Inspection Methods and Limitations

Inspection limited by: • Outdoor faucet (hose bibs/bibbs) not tested due to low outdoor temperature. Ensure water is shut off for the winter, or that frost-free bibs are installed.

Fixtures not tested/not in service: • Outdoor faucet (hose bibs/bibbs) shut off for winter

Items excluded from a building inspection: • Tub/sink overflows

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |

Observations and Recommendations

RECOMMENDATIONS \ General

Condition: • Typical minor flaws were noted on floors, walls and ceilings. These cosmetic issues reflect normal wear and tear.

STAIRS \ Handrails and guards

Condition: • [Hard to hold](#)


The hand rail is not continuously graspable: it pinches along here. Also, it is not plumb.

Location: Basement

Task: Improve

Time: As soon as possible

Cost: Minor



INTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE



Hard to hold



Condition: • Incomplete or not continuous railing

Location: Third Floor

Task: Further evaluation / Improve

Time: As soon as possible

Cost: Minor



Incomplete or not continuous railing

Condition: • [Missing](#)

Location: Second Floor

INTERIOR

140 Jones Ave, Toronto, ON March 13, 2026

Report No. 96443, v.2

www.carsondunlop.com

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

Task: Provide
Time: Immediate
Cost: Minor



Missing

Condition: • [Missing](#)

Location: Third Floor

Task: Provide

Time: As soon as possible

Cost: Minor



Missing

Condition: • [Too low](#)

...only about 29" high.

Task: Improve

Time: As required

Cost: Not determined



Too low



Too low

EXHAUST FANS \ General notes

Condition: • Does not discharge to exterior

Location: Both Kitchens

Task: Improve

Time: As required

Cost: Minor - Each

BASEMENT \ Leakage

Condition: • Almost every basement (and crawlspace) leaks under the right conditions. Based on a one-time visit, it's impossible to know how often or severe leaks may be. While we look for evidence of past leakage during our consultation, this is often not a good indicator of current conditions. Exterior conditions such as poorly performing gutters and downspouts, and ground sloping down toward the house often cause basement leakage problems. Please read Section 10.0 in the Interior section of the Home Reference Book before taking any action. You can find this in the Reference tab at the end of the report.

To summarize, wet basement issues can be addressed in 4 steps:

1. First, ensure gutters and downspouts carry roof run-off away from the home. (relatively low cost)
2. If problems persist, slope the ground (including walks, patios and driveways) to direct water away from the home. (Low cost if done by homeowner. Higher cost if done by contractor or if driveways, patios and expensive landscaping are disturbed.)
3. If the problem is not resolved and the foundation is poured concrete, seal any leaking cracks and form-tie holes from the inside. (A typical cost is \$300 to \$600 per crack or hole.)

4. As a last resort, dampproof the exterior of the foundation, provide a drainage membrane and add/repair perimeter drainage tile. (High cost)

BASEMENT \ Cold room/Root cellar

Condition: • The cold room is in 'as is' condition.

Location: Front Basement

Task: Further evaluation / Improve

Time: As required

Cost: Not determined



OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

Inspection Methods and Limitations

Inspection limited/prevented by: • Storage/furnishings

Not included as part of a building inspection: • Carbon monoxide alarms (detectors), smoke detectors, security systems, central vacuum, window coatings and seals between panes of glass.

Percent of interior foundation not visible: • 75 %


- OVERVIEW
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- RECALCHEK
- OUR ADVICE
- APPENDIX
- REFERENCE

Description

General: • We include a check for product recalls on major appliances at no extra cost. You will receive a separate report from RecallChek with any notices of product recalls and who to contact to get parts replaced, often free of charge. If there are recalls down the road, you will be notified. If you replace the equipment, just let RecallChek know and you will receive recall notices on these too.

Furnace:


- Carrier



Carrier

Water Heater:

- Giant



Giant

Refrigerator:

- Electrolux

- OVERVIEW
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- RECALCHEK
- OUR ADVICE
- APPENDIX
- REFERENCE



Electrolux

- Whirlpool




Whirlpool

Range:

- Whirlpool

- OVERVIEW
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- RECALCHEK
- OUR ADVICE
- APPENDIX
- REFERENCE



Whirlpool

Range: • Haier



Microwave:

• Maytag

- OVERVIEW
 - ROOFING
 - EXTERIOR
 - STRUCTURE
 - ELECTRICAL
 - HEATING
 - COOLING
 - INSULATION
 - PLUMBING
 - INTERIOR
- RECALCHEK
 - OUR ADVICE
 - APPENDIX
 - REFERENCE



Maytag

- Whirlpool



Whirlpool

Description

OUR ADVICE FOR LOOKING AFTER YOUR HOME: • Home maintenance is an important responsibility. It protects your investment, extends life expectancy and helps avoid significant expenses. This document is an integral part of the report, and will help you avoid many common problems and reduce costs.

Priority Maintenance and Home Set-Up: • The Home Set-Up and Maintenance chapter in the Home Reference Book provides important information regarding things that are done once when moving in, as well as regular maintenance activities.

Please be sure to follow these maintenance guidelines. The Home Reference Book is included under the REFERENCE tab in this report.

Basement/Crawlspace Leakage: • Basement water leakage is the most common problem with homes. Almost every basement and crawlspace leaks under the right conditions. Good maintenance of exterior grading, gutters and downspouts is critically important.

For more details, please refer to Section 10 of the Interior chapter of the Home Reference Book, which is in the REFERENCE tab in this report.

Roof - Annual Maintenance: • It is important to set up an annual inspection and tune-up program to minimize the risk of leakage and maximize the life of the roof. Roof leaks may occur at any time and are most often at penetrations or changes in material. A leak does not necessarily mean the roof needs to be replaced.

Roof coverings are disposable and have to be replaced from time to time. Asphalt shingles, for example, last roughly 15 years.

Also, in a mature neighborhood with mature trees, gutters and downspouts can readily become clogged with leaves and debris. Seasonal maintenance and cleaning can help promote adequate drainage from the roof structure and help keep water away from the home and foundation.

Exterior - Annual Maintenance: • Annual inspection of the exterior is important to ensure weather-tightness and durability of exterior components. Grading around the home should slope to drain water away from the foundation to help keep the basement dry.

Painting and caulking should be well maintained. Particular attention should be paid to horizontal surfaces where water may collect.

Joints, intersections, penetrations and other places where water may enter the building assembly should be checked and maintained regularly.

The water supply for all hose bibbs should be shut off from the interior shut-off valve(s) provided and the line(s) drained each season before winter; to help prevent potential freezing of the water supply pipe(s) and subsequent possible flooding issues.

Garage Door Operators: • The auto reverse mechanism on your garage door opener should be tested monthly. The door should also reverse when it meets reasonable resistance, or if the 'photo eye' beam is broken.

Electrical System - Label the Panel: • Each circuit in the electrical panel should be labelled to indicate what it controls. This improves both safety and convenience. Where the panel is already labelled, the labelling should be verified as correct. Do not rely on existing labeling.

Ground Fault Circuit Interrupters and Arc Fault Circuit Interrupters: • These should be tested monthly using the test buttons on the receptacles or on the breakers in the electrical panel.

Heating and Cooling System - Annual Maintenance: • Set up an annual maintenance agreement that covers parts and labour for all heating and cooling equipment. This includes gas fireplaces and heaters, as well as furnaces, boilers and air conditioners. Include humidifiers and electronic air cleaners in the service agreement. Arrange the first visit as soon as possible after taking possession.

Check filters for furnaces and air conditioners monthly and change or clean as needed. Duct systems have to be balanced to maximize comfort and efficiency, and to minimize operating costs. Adjust the balancing for heating and cooling seasons, respectively.

For hot water systems, balancing should be done by a specialist due to the risk of leakage at radiator valves. These valves are not operated during a home inspection.

Bathtub and Shower Maintenance: • Caulking and grout in bathtubs and showers should be checked every 6 months, and improved as necessary to prevent leakage and water damage behind walls and below floors.

Water Heaters: • All water heaters should be flushed by a specialist every year to maximize performance and life expectancy. This is even more critical on tankless water heaters.

Washing Machine Hoses: • We suggest braided steel hoses rather than rubber hoses for connecting washing machines to supply piping in the home. A ruptured hose can result in serious water damage in a short time, especially if the laundry area is in or above a finished part of the home.

Clothes Dryer Vents: • We recommend that vents for clothes dryers discharge outside the home. The vent material should be smooth walled (not corrugated) metal, and the run should be as short and straight as practical. This reduces energy consumption and cost, as well as drying time for clothes. It also minimizes the risk of a lint fire inside the vent.

Lint filters in the dryer should be cleaned every time the dryer is used. There is a secondary lint trap in many condominiums. These should be cleaned regularly. There may also be a duct fan controlled by a wall switch. The fan should be ON whenever the dryer is used.

Dryer ducts should be inspected annually and cleaned as necessary to help reduce the risk of a fire, improve energy efficiency and reduce drying times.

Fireplace and Wood Stove Maintenance: • Wood burning appliances and chimneys should be inspected and cleaned before you use them, and annually thereafter. We recommend that specialists with a WETT (Wood Energy Technology Transfer, Inc.) designation perform this work. Many insurance companies require a WETT inspection for a property with a wood burning device.

Smoke and Carbon Monoxide (CO) Detectors/Alarms: • Smoke detectors are required at every floor level of every home, including basements and crawlspaces. Even if these are present when you move into the home, we recommend replacing the detectors. We strongly recommend photoelectric smoke detectors rather than ionization type detectors. Carbon monoxide detectors should be provided adjacent to all sleeping areas.

These devices are not tested during a home inspection. Detectors should be tested every 6 months, and replaced every 10 years. Batteries for smoke and carbon monoxide detectors should be replaced annually. If unsure of the age of a smoke detector, it should be replaced.

Backwater Valve: • A backwater valve protects your home from a backup of the municipal sewer system. The valve may be equipped with an alarm to notify you of a backup. Please note: if the valve is closed due to a municipal sewer backup, you cannot use the plumbing fixtures in the home. The waste water is unable to leave the building and will back up through floor drains and the lowest plumbing fixtures. • The valve should be inspected and cleaned as necessary at least twice a year.

Sump Pump: • A sump pump collects storm water below the basement floor and discharges it safely to the exterior to prevent flooding. The discharge point should be at least 6 feet (2 m) away from the home. Best installations include backup power for the sump pump, so it will work in the event of a power outage. A high water alarm in the sump pump will notify you if the pump fails. Some installations include a backup pump.

The sump and pump should be inspected and tested four times a year.

For condominium owners: • Condominium owners - Maintenance and Repairs: There are two types of repairs that may be performed in a condo - repairs to an individual condo unit and repairs to common elements. Common elements are set out in the Condominium Declaration and will differ from one building to another. If repairs must be made inside your unit, you are responsible for making the repairs at your own expense. You are also responsible for the ongoing maintenance of your unit. The condominium corporation's board of directors is responsible for maintenance and repair of the common elements. Exclusive-use common elements, such as parking spaces or balconies are generally maintained by the condominium board.

Be Ready for Emergencies: Be sure you know where to shut off the water. Some condos have more than one shut off, and others need a special tool (key) to turn off water. Label each circuit on the electrical panel, and make sure you should know how to turn off the power. Keep a fire extinguisher suitable for grease fires near the kitchen.

Property Manager and Concierge/Security: Keep the contact information for these folks handy (perhaps on your phone) wherever you are. • Lint filters in the dryer should be cleaned every time the dryer is used. There is a secondary lint trap in many condominiums. These should be cleaned regularly. There may also a duct fan controlled by a wall switch. The fan should be ON whenever the dryer is used.

END OF REPORT

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |

Investments. Insurance. Advice. All in one place.

For more than 75 years, we've been helping Canadians, like you, build financial security. Whether you're looking for investments, insurance or both, count on us for the personalized advice and solutions you need to keep what matters safe and save for what matters. Let us help you with:



Investments

Choose from straightforward saving and investing options to help you achieve financial success, however you define it.



Business

Design a plan that protects what you've worked so hard to build. And access unique services that help your business grow.



Life

Protect your loved ones, your assets and your financial future, with the right type and amount of coverage.



Farm

Secure your property and your livelihood, with a plan that accounts for the specifics of your farming operation.



Home

Keep your living space and everything within it safe, with a customized policy for your home, condominium or cottage.



Travel*

Enjoy affordable coverage, whether you're travelling for work or play, and whether it's a short visit or an extended stay.



Auto

Get coverage that factors in what you drive, when you drive, and discounts for a clean driving record. Add a policy for greater savings!



Group Benefits

Up your competitive edge, with a plan that supports the health and well-being of your most important asset: your employees.

Ready to build your financial future?

Talk to us about creating a plan that meets your needs for today and your goals for tomorrow.

RJB Insurance Group Inc.

30-1029 King Street West, Toronto
416-264-2281
rjb_insurance@cooperators.ca

Vel Insurance Services Inc.

708-10 Milner Business Court, Toronto
416-396-0707
vel_insurance@cooperators.ca

Investments. Insurance. Advice.



Co-operators Financial Investment Services Inc.

*Travel offered is both inbound and outbound travel and is administered by Allianz Global Assistance.

Mutual funds are offered through Co-operators Financial Investment Services Inc. to Canadian residents except those in Québec and the territories. Life products and Group Benefits plans are underwritten by Co-operators Life Insurance Company. Home, Auto, Commercial and Farm insurance is underwritten by Co-operators General Insurance Company. Not all products are available in all provinces. Please refer to your policy for applicable coverage limitations and exclusions. Co-operators General Insurance Company, Co-operators Life Insurance Company, and Co-operators Financial Investment Services Inc. are committed to protecting the privacy, confidentiality, accuracy and security of the personal information that we collect, use, retain and disclose in the course of conducting our business. Please visit www.cooperators.ca/en/PublicPages/Privacy.aspx for more information.

© 2022 Co-operators Life Insurance Company. © 2022 Co-operators Financial Investment Services Inc. © 2022 Co-operators® is a registered trademark of The Co-operators Group Limited. EIM0007 (10/22)




As a Carson Dunlop client, you are entitled to many useful discounts and perks from some of our home service partners.



Woodbridge GTA ClimateCare (\$160 value)

- Get a **FREE** safety inspection and tune-up on your home's heating or cooling systems (your choice)
- Claim your \$160 value tune-up by calling [905-851-7007](tel:905-851-7007) or emailing info@gtacclimatecare.com



\$70 gift card from 1-800-GOT-JUNK?

Carson Dunlop clients receive a \$70 gift card for junk removal services.

| | | | | | | | | | |
|-----------|------------|----------|-----------|------------|---------|---------|------------|----------|----------|
| OVERVIEW | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RECALCHEK | OUR ADVICE | APPENDIX | REFERENCE | | | | | | |




THREE STEPS TO COST-EFFECTIVE HOME FLOOD PROTECTION


Complete these 3 steps to reduce your risk of flooding and lower the cost of cleanup if flooding occurs. For items listed under step 3 check with your municipality about any permit requirements and the availability of flood protection subsidies. **Applicable only in homes with basements*

Step 1: Maintain What You've Got at Least Twice per Year


Do-it-Yourself for \$0




Remove debris from nearest storm drain or ditch & culvert




Clean out eaves troughs



Check for leaks in plumbing, fixtures and appliances




Test your sump pump*




Clean out your backwater valve

Step 2: Complete Simple Upgrades


Do-it-Yourself for Under \$250




Install window well covers (where fire escape requirements permit)*




Extend downspouts and sump discharge pipes at least 2m (6.5') from foundation



Store valuables and hazardous materials in watertight containers & secure fuel tanks




Remove obstructions to floor drain




Install and maintain flood alarms

Step 3: Complete More Complex Upgrades


Work with a Contractor for Over \$250




Install window wells that sit 10-15cm (4-6") above ground and upgrade to water resistant windows*




Disconnect downspouts, cap foundation drains and extend downspouts to direct water at least 2m from foundation



Correct grading to direct water at least 2m away from foundation



Install backwater valve



Install backup sump pump and battery*

Note: Not all actions will be applicable to each home. Completing these steps does not guarantee the prevention of flooding.



Basement Flood Protection Checklist

Take these steps to reduce your risk of basement flooding and reduce the cost of cleaning up after a flood. Remember to check with your municipality about the availability of basement flood protection subsidies. Check with your insurer about discounts for taking action to reduce flood risk.

1. Maintain Your Home’s Flood Protection Features at Least Twice Per Year

SPRING FALL

- Remove debris from nearest storm drain
- Clean out eaves troughs
- Test sump pump(s) and backup power source
- Clean out backwater valve
- Maintain plumbing, appliances and fixtures
- Test flood alarms

2. Keep Water Out of Your Basement

- Correct grading to direct water at least 2m away from your foundation
- Extend downspouts and sump discharge pipes to direct water at least 2m away from your foundation or to the nearest drainage swale
- Install window well covers
- Install window wells that are 10-15cm above the ground and are sealed at the foundation
- Install water-resistant basement windows
- Install a backwater valve (work with a plumber and get required permits)

3. Prepare to Remove Any Water from Your Basement as Quickly as Possible

- Remove obstructions to the basement floor drain
- Install a back-up sump pump and power source

4. Protect Personal Belongings in Your Basement

- Store valuables in watertight containers or remove
- Store hazardous materials (paints, chemicals) in watertight containers or remove
- Raise electronics off the floor
- Select removable area rugs and furnishings that have wooden or metal legs

Note: Not all actions will be applicable to each home. Completing these steps does not guarantee the prevention of basement flooding.

OVERVIEW

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

RECALCHEK

OUR ADVICE

APPENDIX

REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS

