

Home Inspection Report

# Prepared exclusively for **Kevin Hoch**



PROPERTY INSPECTED: 445 Crawford Street Toronto, ON M6G 3J7

Date of Inspection: 11/16/2023 Inspection No. 141126-2318

## **INSPECTED BY:**

Allen Ottaway 160 Goodman Dr. Oshawa, ON L1J 7V8 <u>allen.ottaway@pillartopost.com</u> (647) 284-4486

## **INSPECTOR:**

Allen Ottaway allen.ottaway@pillartopost.com (289) 240-1189

Each office is independently owned and operated

# **INSPECTION REPORT**

## **1.0** INTRODUCTION

## 1.1 General Information

1.1.1 This is a pre-listing inspection performed for the seller of the home in preparation for putting the home on the market for sale. This inspection is completed to CSA standards, is visual in nature, and does not address building code compliance issues which are the purview of municipal building inspectors.

#### 1.2 Inspector

1.2.1 Allen Ottaway 647-284-4486

## 1.3 Scope of Inspection

1.3.1 This home inspection is done in accordance with the CSA standard.

CSA A770-16 Home Inspection was developed to help establish specific guidance for inspection through a single recognized standard. Inconsistency in the approach to inspections can create a risk for both consumers and home inspectors, and the lack of clear expectations for what a home inspection entails may cause increased liability for both parties. The CSA Group technical committee, comprised of a balanced representation of stakeholders including real estate agents, home inspectors, consumer protection groups, governments and others, agreed that a national standard would help provide clarity. A home inspection is intended to be a non-invasive evaluation of the condition and performance of systems and components of a dwelling, and is often carried out when buying or selling a home. It is primarily used to identify and report any items that may be faulty, and the focus is on significant issues that are readily visible to the inspector as opposed to minor building deficiencies. The new standard offers benefits to both consumers and home inspectors. While the standard is not mandatory, by adopting it home inspectors will have a better defined, clear set of requirements to stand behind when disagreements arise. Widespread implementation of the CSA standard will help inspectors to provide the best possible service to clients on a level playing field. Home buyers will have a clearer sense of what a home inspection entails and a better understanding of the scope and purpose of the service, and may seek out inspectors who can conduct an inspection to the benchmark of the standard.

## 1.4 Inspection / Site Conditions

Sunny

1.4.1 Home is a two storey detached structure. Temporary at t8me of inspection is 7 Celsius

## 2.0 PROPERTY AND SITE

#### 2.1 Limitations

▲ Parked car(s) limited the inspection of the driveway.

## 2.2 Site Overview

2.2.1 The property / grounds / site were inspected. Any visible issues, along with other pertinent comments, are listed below.

## 2.3 Landscape / Grading

2.3.1 The general landscape such as grading and surface water drainage was inspected.

## 2.4 Walkway(s)

Pavers

2.4.1 All walkways on the property were inspected.

## 2.5 Driveway(s)

Pavers

## 3.0 EXTERIOR

## 3.1 Exterior General Comments

 $\odot$   $\;$  Exterior wall elevations were inspected with binoculars from ground level.

3.1.1 The exterior components were inspected from the ground level. Any visible issues, along with other pertinent comments, are listed below.

Example views of the exterior can be seen in the picture(s) below.



11/16/2023



## 141126-2318 445 Crawford Street, Toronto, ON M6G 3J7

#### 3.2 Foundation Surface

- $\odot$   $\;$  Foundation surface is parged (coated with cementitious material).
- ⊘ The visible portions of the exterior foundation walls were inspected.
- 3.2.1 Exterior wall has been waterproofed



## 3.3 Wall Surface

- Wood siding
- Brick
- Stucco
- $\odot$  The visible portions of the exterior wall surfaces were inspected
- 3.3.1 Exterior wall surfaces were inspected from ground level.

3.3.2 Surface deterioration of brick/mortar noted is common at this age. Repair worn areas, repoint open joints to repel water, reduce further deterioration. Anticipate occasional repairs as part of owning an old property.



## 3.4 Eaves / Fascia / Soffit

- Aluminum Eaves
- ⊘ Aluminum Soffit
- 3.4.1 Inspected from ground level.

## 3.5 Windows

3.5.1 Exterior window frames and trim inspected from ground level.

3.5.2 Windows upgraded at some point. Some dated 2023. Functioning as intended. Periodically check, caulk seams to maintain.

## 3.6 Exterior Doors

3.6.1 Inspected and functional

## 3.7 Deck(s)

⊘ Wood

3.7.1 The deck was inspected

## 4.0 ROOFING SYSTEM

## 4.1 Roofing General Comments

4.1.1 This is a visual inspection limited in scope by (but not restricted to) the following conditions:

• The entire underside of the roof sheathing is not inspected for evidence of leakage.

- · Evidence of prior leakage may be disguised by interior finishes
- · Leakage can develop at any time and may depend on rain intensity and/or wind direction

• Roof inspection may be limited by the type of roof coverings, access, roof condition, weather, etc.

Please also refer to the visual inspection agreement for a detailed explanation of the scope of this inspection.

4.1.2 Example view(s) of the roof can be seen in the pictures below





## 4.2 Roofing Inspection Method

 $\odot$   $\;$  Inspected from ground with binoculars / camera zoom.

## 4.3 Sloped Surface(s)

- Asphalt shingles
- 4.3.1 Seller advises architectural shingles are 1 year old. No visible defects

#### 4.4 Flat Surface(s)

Modified bitumen

4.4.1 Seller advises flat roof membrane is 1 year old . No visible defects

#### 4.5 Flashings

Plumbing stack

The visible flashings were inspected

4.5.1 Periodically check and re caulk flashings to repel water. Upgrade as needed when replacing the shingles.

## 4.6 Roof Drainage

- O Above ground drainage
- Aluminum Eaves

4.6.1 Gutters are full of leaves and debris. Clean and remove debris from gutters for proper drainage off roof. This is an ongoing maintenance requirement that should be completed twice a year or as required.

## 5.0 ATTIC

#### 5.1 Limitations

▲ The exhaust ducts were concealed

## 5.2 Attic General Comments

5.2.1 This is a visual inspection limited in scope by (but not restricted to) the following conditions:

• Insulation/ventilation type and levels in concealed areas are not inspected. Insulation and vapor barriers are not disturbed. No destructive tests are performed.

• No access was gained to the wall cavities of the home. • Any estimates of insulation R-values or depths are rough average values

5.2.2 Example views of the attic can be seen in the picture(s) below.





#### 5.3 Attic Access

Pulldown Ladder

#### 5.4 Insulation

5.4.1 Approximately 10 inches of fibreglass insulation

#### 5.5 Ventilation

- Roof Vents
- Soffitt

## 5.6 Vapor Barrier

Not Visible from Hatch

## 5.7 Sheathing

Boards

6.0 STRUCTURE

## 6.1 Limitations

△ Interior foundation wall not visible due to finishings

## 6.2 Structure General Comments

6.2.1 This is a visual inspection limited in scope by (but not restricted to) the following conditions:

• A representative sampling of visible structural components was inspected. Concealed or inaccessible structural components are not inspected (including items underground or contained inside walls, concrete slabs, or other closed portions of the building) or concealed by fixtures, appliances, furnishings, personal property.

• Termites, wood boring insects, dry rot, fungus, rodents, or other pests are outside the scope of this inspection.

• Engineering or architectural services such as calculation of structural capacities, adequacy, or integrity are not part of a home inspection. Please also refer to the visual inspection agreement for a detailed explanation of the scope of this inspection.

## 6.3 Support - Post / Beam / Column

Masonry support columns

#### 6.4 Floor Structure

- ⊘ Wood dimensional lumber.
- Slab on grade

## 6.5 Wall Structure

⊘ Solid masonry

#### 6.6 Roof Structure

- Rafters
- ⊘ Plank / board roof sheathing.

## 6.7 Basement

Finished Basement

6.7.1 Basement structure material/conditions determined by representative amount as visible in furnace/laundry utility room. Less than 10% of components visible

## 7.0 ELECTRICAL SYSTEM

## 7.1 Electrical General Comments

7.1.1 This is a visual inspection limited in scope by (but not restricted to) the following conditions:

Most of the service cable and distribution wiring is concealed.

• A representative sampling of outlets and light fixtures were tested. Concealed electrical components could not be inspected.


The inspection does not include remote control devices, alarm systems and components, low voltage wiring, systems, and components, ancillary wiring systems, antennae, computer wiring, satellite or cable TV systems
Fire sprinklers, smoke alarms/detectors and carbon monoxide detectors are not inspected or tested.

Please also refer to the visual inspection agreement for a detailed explanation of the scope of this inspection.

## 7.2 Service Entrance

Electrical service voltage is 240 volts

7.2.1 Electrical service to home is by overhead cables.



7.3 Service Size


7.3.1 200 Amp Service

## 7.4 Main Disconnect(s)

⊘ Breaker

7.4.1 The disconnect device was inspected visually but not operated

7.4.2 Main disconnect noted in picture



## 7.5 Distribution Panel(s)

- ⊘ Breaker panel
- Panel Rated at 200A
- 7.5.1 The accessible distribution panel(s) and overcurrent protection devices were inspected

7.5.2 200 amp service. breaker panel is full . One low voltage double tap. No significant visible defects inside the panel.

## 7.6 Grounding

⊘ Grounded at water main.

## 7.7 Branch Circuit Wiring

- ⊘ Copper wire branch circuits.
- ⊘ Grounded wiring
- ⊘ Copper Non-Metallic Sheathed Wire

## 7.8 Receptacles

- $\odot$   $\;$  A representative number of accessible receptacles were tested.
- 7.8.1 Tested and functional
- 7.8.2 Receptacles tested are grounded

## 7.9 Lighting / Ceiling Fan(s)

⊘ A representative number of lighting fixtures and switches were inspected

7.9.1 Functional

## 7.10 Exhaust Fan(s)

- ⊘ The exhaust fan(s) were tested on / off.
- 7.10.1 Functional

## 7.11 GFCI Devices

7.11.1 Functional

7.11.2 A ground fault circuit interrupter device protects users from receiving electric shocks in the electrical devices used around the home and in particular in damp locations.



#### 7.12 Smoke Alarms

7.12.1 Smoke detectors are required on all levels. Test on a monthly basis.

#### 7.13 Carbon Monoxide Alarms

7.13.1 Safety Tip: We strongly recommend that you have a carbon monoxide detector installed in any room that has gas and within 15 feet of any bedroom as required by law in Ontario. These can be purchased at any hardware store for approximately \$50.

Consider replacing CO alarms when taking possession to ensure that new, properly functioning and properlylocated protection is in place.

## 8.0 HEATING/COOLING/VENTILATION SYSTEM(S)

#### 8.1 Limitations

▲ A/C is not tested when outside temperatures are below 15°C as per standard of practice. Unit will need to be tested when conditions permit

## 8.2 HVAC General Comments

8.2.1 HVAC units are inspected by opening readily accessible user-removable panels. Panels on package (one piece) units are not readily removable, and are not removed during the inspection. Defects or failure of HVAC equipment can happen at anytime, without warning, including the day after the inspection. We strongly recommend that you have all HVAC equipment cleaned and serviced as soon as you move in and twice a year after that. Regular service is very important for efficient operation and to achieve maximum service life. Most AC and heat pump compressors carry manufacturers' warranties of no more than 5 years. The report should not be read a prediction of the remaining life span of the HVAC system. If you want protection against HVAC system breakdowns, we recommend that you purchase a warranty or service contract on your HVAC equipment.

## 141126-2318 445 Crawford Street, Toronto, ON M6G 3J7

## 8.3 Thermostat(s)

8.3.1 Ecobee thermostat located on main floor



## 8.4 Energy Source(s)

Natural Gas

8.4.1 Gas shutoff valve is located at the unit.



#### 8.5 Meter

- Natural Gas
- 8.5.1 Located at right side of home



## 8.6 AC / Heat Pump System(s)

Air Conditioning System

8.6.1 Air conditioner is dated 2012


System not tested due to low outdoor temperature. Determine function in cooling season



## 8.7 Forced Air Furnace(s)

8.7.1 System was tested by using normal operating controls.

8.7.2 High efficiency furnace is dated 2022 and is functional



## 8.8 Combustion/Venting

- ⊘ Gas 636 pipe
- Exhaust is vented to exterior foundation wall

## 8.9 Natural Gas Piping

8.9.1 External gas connection



## 9.0 PLUMBING SYSTEM

## 9.1 Limitations

△ The exterior hose bibs could not be operated as they are winterized.

## 9.2 Plumbing General Comments

9.2.1 This is a visual inspection limited in scope by (but not restricted to) the following condition:

• Concealed portions of the plumbing system could not be inspected, including the subterranean systems and/or system components of the sewage disposal, water supply, and fuel storage or delivery systems. Please also refer to the visual inspection agreement for a detailed explanation of the scope of this inspection. The visible plumbing piping and plumbing fixtures were inspected and tested. Any visible issues, along with other pertinent comments, are listed below.

## 141126-2318 445 Crawford Street, Toronto, ON M6G 3J7

#### 9.3 Water Main

- O Main water shut-off valve is in the basement.
- Metered
- 9.3.1 Inspected the visible portion of the house water main.
- 9.3.2 Copper water main.



## 9.4 Distribution Piping

- ⊘ Interior water supply pipes are copper.
- ⊘ Interior water supply pipes are plastic.
- 9.4.1 The visible portions of the water distribution piping was inspected.
- 9.4.2 The water flow was observed with multiple fixtures operating. Water flow / pressure drop was typical.

## 9.5 Drain, Waste, and Vent Piping

- Plastic
- 9.5.1 The visible portions of the interior drain, waste and vent system were inspected.

## 9.6 Water Heating Equipment

- Storage tank hot water system.
- 189 Litres
- ⊘ Fuel source is natural gas.
- Water heater is located in the basement
- Rental
- 9.6.1 The domestic hot water system was inspected and operated.

9.6.2 Water heater is dated 2017 and is functional



#### 9.7 Water Heater Venting

9.7.1 The combustion and venting of the water heating equipment was inspected.

9.7.2 Power vented to exterior. Pipe is secured and in good condition.

#### 9.8 Fixtures / Faucets

9.8.1 Functional

#### 9.9 Sink(s)

- ⊘ The sink(s) were inspected and operated.
- 9.9.1 Sinks and tubs were filled to test drainage. No defects found.

## 9.10 Toilet(s)

- ⊘ The toilet(s) were inspected and operated.
- 9.10.1 Functional

## 9.11 Tub(s) / Shower(s)

- 9.11.1 Tubs and showers were inspected and operated and are functional.
- 9.11.2 Light pressure was applied to shower walls to ensure stability. No defects found.

## 9.12 Floor drain

9.12.1 Drainage was tested by filling several sinks /tubs and flushing toilets. No issues with drainage at time of inspection.

## **10.0** INTERIOR

## **10.1** Interior General Comments

10.1.1 This is a visual inspection limited in scope by (but not restricted to) the following conditions:carpeting, window treatments, paint, wallpaper, and other finish treatments are not inspected. Please also refer to the Visual Inspection Agreement for a detailed explanation of the scope of this inspection.

## 10.2 Floors

⊘ The flooring was inspected where visible.

## 10.3 Walls / Ceilings

- Drywall
- $\odot$  The walls and ceilings were inspected where visible.

#### 10.4 Windows

- O A representative sample of the visible and accessible windows were inspected
- Thermal Pane

## 10.5 Doors

⊘ A representative number of doors were inspected

10.5.1 Functional

## 10.6 Stairs / Railings / Guardrails

⊘ Steps, stairways, and/or railings were inspected where visible and accessible.

#### 10.7 Countertops / Cabinets

O Countertops and a representative number of installed cabinets were inspected.

#### 10.8 Heating / Cooling Sources

- Forced Air
- Radiant
- 10.8.1 In floor heating in entryway and second floor washroom

## **11.0** FIREPLACE(S)

## 11.1 Gas Insert(s)

11.1.1 Functional gas fireplace



12.0 APPLIANCES

## 141126-2318 445 Crawford Street, Toronto, ON M6G 3J7

## 12.1 Appliance General Comments

12.1.1 All appliances were turned on using regular operating controls if they are connected or not shut down. All functions and different systems are not tested. The test simply comprises turning the appliances on to verify some basic functionality.

#### 12.2 Refrigerator

- 12.2.1 Functional
- 12.2.2 Kitchenaid



# 12.3 Ranges / Ovens / Cooktops

12.3.1 Functional

12.3.2 Kitchenaid electric range Seller advises there is a gas connection installed



- 12.4 Range Hood 12.4.1 Functional
- **12.5 Dishwasher** 12.5.1 Functional

12.5.2 Bosch



## 12.6 Clothes Washer

- 12.6.1 Functional
- 12.6.2 General Electric (Second floor)



12.7 Clothes Dryer 12.7.1 Functional

## 12.7.2 General Electric

Dryer vent cleaning is recommended to increase efficiency and for fire safety. Inspect/clean on a regular basis.

Interior of dryer vent condition concealed-not inspected (Second floor)



- 13.0 GENERAL COMMENTS ABOUT THIS INSPECTION
- 13.1 Limitations

13.1.1 This report has been prepared based upon the Standards of Practice established by the CSA. All components designated for inspection in the CSA Standards of Practice, adopted March 2019 are inspected, except as may be noted within this report. Representative samples of building components are viewed in areas that are readily accessible at the time of the inspection. No destructive testing or dismantling of building components is performed. This inspection is visual only. The purpose of this inspection is to identify and disclose visually observable major deficiencies of the inspected systems and items at the time of the inspection. Detached structures or buildings are not included. This inspection is not intended to be technically exhaustive nor is it considered a guarantee or warranty, expressed or implied, regarding the conditions of the property, items and systems inspected. The inspection and report should not be relied on as such. The Inspector shall not be held responsible or liable for any repairs or replacements with regard to this property, systems, components, or the contents therein. Pillar To Post operated by ARO Inspections Inc. is neither a guarantor nor insurer. Not all improvements will be identified during this inspection. The inspection and related report do not address and are not intended to address code and/or regulation compliance, environmental hazards including: mold, mildew, fungus, indoor air quality, asbestos, radon gas, lead paint, urea formaldehyde, soils contamination, cockroaches, rodents, pesticides, treated lumber, mercury and any other indoor or outdoor substances. The client is urged to contact a competent specialist if information, identification or testing of the above is desired. The acceptance of this report by the client acknowledges the client's agreement to all of the terms and conditions of the visual inspection agreement. Please refer to the inspection agreement for a full explanation of the scope of the inspection.

The contents of this report are for the sole use of the client who paid for this report and no other person or party may rely on this report for any reason or purpose whatsoever without the prior written consent of the inspector who authored the report. Any person or party who chooses to rely on this report for any reason or purpose without the express written consent of ARO Inspections Inc does so at their own risk and by doing so without the consent of ARO Inspections Inc waives any claim of error or deficiency in the report.

This inspection does not include: Low voltage systems, telephone wiring, intercoms, sound systems, central vac systems, sprinkler systems, alarm systems, cable- or satellite- TV wiring, timers or smoke detectors. Prior to closing, request that the seller provide warranty documentation, instructions & receipts for any installed or remaining systems and appliances.

The Report Commentary is provided to allow the reader a brief overview of the Report. This page is not all encompassing. Reading this page alone is not a substitute for reading the report in its entirety. The entire Inspection Report, including the Standards of Practice of the American Society of Home Inspectors, limitations, Scope of Inspection and Inspection Agreement must be carefully read to fully assess the findings of the Inspection. This list is not intended to determine which items may need to be addressed per the contractual requirements of the sale of the property. Any areas of uncertainty regarding the contract should be clarified by consulting an attorney or real estate agent. It is recommended that any deficiencies and the components / systems related to these deficiencies noted in the Report be evaluated / inspected and repaired as needed by licensed contractors / professionals prior to the close of the sale. Further evaluation prior to closing is recommended so a properly licensed professional can evaluate our concerns further and inspect the remainder of the system or component for additional concerns that may be outside our area of expertise or the scope of our inspection. Please call our office for any clarification or further questions.